

Safety Gate home (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/repository/content/pages/rapex/index\_en.htm)

E Back to report listings (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/?event=main.listNotifications&year=2020&lng=er

Q Search alerts (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/?event=main.search&Ing=en)

IPSW 2018 (https://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/?event=ipsw:home)

## The Rapid Alert System for Non-Food Products (RAPEX)

## **RAPEX - Weekly overview report of notifications**

Week 41 - 2020

null

Alert number: A12/01319/20 Product: Plastic stool Name: Risk type: Injuries Category: Furniture Brand: ER-ER Type / number of model: Code 074 Type of alert: Products with serious risks The plastic stool is not sufficiently resistant to load. It may break down and cause the user to fall increasing the risk of injuries. / The product does not comply with EN 1728: 2012 and EN 581-2: 2015 / AC: 2016 Ban on the marketing of the product and any accompanying measures Description: Small stools, plastic, brown color with a surface imitating knitting (rattan type). Batch number / Barcode: 8699952640741 NO Country of origin: Turkey Alert submitted by: Bulgaria ÜCÜK HASIR TABURE

Alert number: A12/01321/20 Product: Nicotine containing liquid cartridges Name: Cart Co Risk type: Chemical Category: Chemical products Brand: Cart Co USA Type / number of model: 16 mg/ml nicotine strength , 20 mg/ml nicotine strength Type of alert: Products with serious risks This product contains nicotine (up to 20 mg/ml), which is classified as acutely toxic, but it does not have a leaflet providing the consumer with information about safe and correct use of the product, contraindications and adverse effects. The user also has no information to avoid the dangers incurred when the product comes into contact with the skin or if it is ingested. / The product does not comply with the requirements of the Tobacco Products Directive. Other, Recall of the product from end users, Withdrawal of the product from the market Company recall page: https://www.vipelectroniccigarette.ie (https://www.vipelectroniccigarette.ie) Description: The product contains 5 units of 1 ml prefilled cartridges. Batch number / Barcode: 0 768114 956216 NO

Country of origin: United Kingdom

Alert submitted by: Ireland



Alert number: A12/01327/20 Product: Soldering wire Name: Silverline Solder Risk type: Chemical Category: Chemical products Brand: Silverline Type / number of model: 701153, AS15 Type of alert: Products with serious risks The soldering wire contains lead (measured value: 60 % by weight) and is not correctly labelled to indicate it is restricted to professional users. Exposure to lead is harmful for human health. / The product does not comply with REACH Regulation. Withdrawal of the product from the market Description: Soldering wire (100g and 250g). The product was sold online, in particular via eBay. Batch number / Barcode: UNKNOWN Country of origin: Unknown Alert submitted by: Ireland SILVERLINEC Alert number: A12/01320/20 Product: Flail-type cutting attachment for brush cutter Name: 6 Tooth Brush Cutter Brushcutter Electric Garden Trimmer Strimmer Mower Blade Risk type: Cuts, Injuries Category: Machinery Brand: Type / number of model: Type of alert: Products with serious risks The rivets attaching the cutting knives to the blade could break. The knives might consequently detach during use and hit the user. / The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters. Recall of the product from end users Description: Flail-type cutting attachments consisting of several linked metal parts for portable hand-held brush cutters. The product was sold online, in particular via Wish.com. Batch number / Barcode: NO Country of origin: Unknown Alert submitted by: Denmark

Alert number: A12/01344/20 Product: Flail-type cutting attachment for brush cutter Name: 6 Teeth Grass Steel Trimmer Head Brush Cutter Risk type: Cuts, Injuries Category: Machinery Brand: Type / number of model: Type of alert: Products with serious risks The rivets attaching the cutting knives to the blade could break. The knives might consequently detach during use and hit the user. / The product does not comply with the requirements of the Machinery Directive and Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters. Recall of the product from end users Description: Flail-type cutting attachments consisting of several linked metal parts for portable hand-held brush cutters. The product was sold online. Batch number / Barcode: NO Country of origin: Unknown Alert submitted by: Denmark Alert number: A12/01317/20 Product: Pickup truck Name: X-Class **Risk type: Injuries** Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval number: e1\*2007/46\*6531\*00 - \*01, Type: 4701 Type of alert: Products with serious risks The child safety lock on the rear doors could come loose unnoticed, as a result of which the rear doors could be opened from the inside. / Recall of the product from end users Description: Batch number / Barcode: VS4SIKIND (7290253) NO Country of origin: Germany Alert submitted by: Germany Alert number: A12/01318/20 Product: Passenger car Name: 508 **Risk type: Injuries** Category: Motor vehicles Brand: Peugeot Type / number of model: Type-approval number: e2\*2007/46\*0628\*01-04, 06, Type: F Type of alert: Products with serious risks The brake hoses on the rear axle can be damaged by coming into contact with the wheel rims. This can cause brake fluid to leak out, increasing the risk of an accident. / Recall of the product from end users Description: Batch number / Barcode: JXF NO Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Poland

Alert number: A12/01326/20 Product: Passenger van / Light commercial vehicle Name: NV300 Risk type: Injuries Category: Motor vehicles Brand: Nissan Type / number of model: Type-approval numbers: e2\*2007/46\*0037, e2\*98/14\*0271 , Types: 4, J4 Type of alert: Products with serious risks The parking brake lever bearing bolt may break when the parking brake is used. This can lead to an unintended movement of the vehicle, increasing the risk of an accident. / Recall of the product from end users Description: Batch number / Barcode: PN9B6 NO Country of origin: France Alert submitted by: Germany Products were found and measures were taken also in: Greece, Ireland Alert number: A12/01333/20 Product: Vehicle part - breakaway cable Name: NA35, NA35HV, NA30 **Risk type: Injuries** Category: Motor vehicles Brand: Nieper Type / number of model: Type-approval numbers: E1 55R - 011545, E1 55R - 011546, E1 55R - 011644 Types: NA35, NA35HV, NA30 Type of alert: Products with serious risks The breakaway cable may be defective. This can cause the emergency brake function to fail in the event of a trailer separation, leading to increased risk of an accident. / Recall of the product from end users Description: Breakaway cable that connects the trailer's brake-release mechanism to the towing vehicle. Batch number / Barcode: 2020-NA-RR NO Country of origin: Germany Alert submitted by: Germany Alert number: A12/01334/20 Product: Pickup truck Name: Amarok **Risk type: Injuries** Category: Motor vehicles Brand: VW Type / number of model: Type-approval number: e1\*2007/46\*0356\*, Type: 2H Type of alert: Products with serious risks The winch rope that is used to attach the spare wheel under the vehicle and the additional strap fitted as a secondary safety device may break. This may cause the spare wheel to fall onto the road, posing a risk to the following traffic. / Recall of the product from end users Description: Batch number / Barcode: 66L9, 66M1 NO Country of origin: Germany Alert submitted by: Germany

Alert number: A12/01336/20 Product: Passenger car Name: C-Class, CLS, E-Class, GLC, S-Class Risk type: Fire, Injuries Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval numbers: e1\*2001/116\*0431\*42, 54-56; e1\*2001/116\*0501\*42-43; e1\*2007/46\*1666\*14-15; e1\*2001/116\*0480\*33-38; e1\*2007/46\*1818\*07, Types: 204, 212, R1EC, 204 X, R1ECLS Type of alert: Products with serious risks Due to the lack of documentation, there is no confirmation that the screw connections of the turbocharger's oil-supply and oil-return pipes were correctly executed during the assembly process. In the event of a loose screw connection, oil might leak at the oil-supply and/or oil-return pipe of the turbocharger. The leaking oil might then come into contact with hot components, increasing the risk of fire. / Recall of the product from end users Description: Passenger cars with with a 4-cylinder petrol engine; Model series: BR 205, 213, 238, 222, 253, 257 Batch number / Barcode: 0993103 NO Country of origin: Germany Alert submitted by: Germany Products were found and measures were taken also in: Greece, Ireland Alert number: A12/01337/20 Product: Passenger car Name: A-Class, B-Class, CLA, GLA, GLB Risk type: Fire Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval numbers: e1\*2007/46\*1912\*03-04, e1\*2007/46\*1829\*07-08, e1\*2007/46\*1909\*03-04, Types: F2CLA, F2A, F2B Type of alert: Products with serious risks The oil-supply pipe on the turbocharger may leak. As a result, engine oil could leak onto the under-body paneling and from there onto the road, posing a risk to the following traffic. Moreover, leaking engine oil might come into contact with hot components in the engine compartment, increasing the risk of fire. / Recall of the product from end users Description: Vehicles with a 4-cylinder M282 petrol engine, model series: A-Class (BR 177), B-Class/GLA/GLB (BR 247) and CLA (BR 118). Batch number / Barcode: 0993022 NO Country of origin: Germany Alert submitted by: Germany Products were found and measures were taken also in: Greece, Ireland Alert number: A12/01338/20 Product: Passenger car Name: GLE, GLS **Risk type: Injuries** Category: Motor vehicles Brand: Mercedes-Benz Type / number of model: Type-approval numbers: e1\*2007/46\*1885\*00 to \*03, Types: H1GLE Type of alert: Products with serious risks The windscreen may be incorrectly bonded could become detached from the body of the car in the event of a crash. A passenger airbag being deployed in this case could not be supported by the windscreen as intended. As a result, the restraining effect of the passenger airbag could be impaired, increasing the risk of injury to the passenger. / Recall of the product from end users Description: GLE and GLS vehicles, model series BR 167. Batch number / Barcode: 6790001 NO Country of origin: Germany

Alert submitted by: Germany

Aler number - A120138200 Name - Expansibility of incomedy website Gategory, Motor vehicles Bond: WW Type / number of model: Type approval number: of 12001/110/450°, Type: SN Yope / atter: Products website and an expansion of the backwest frame of the foot seat may be fauly or incomedy website. As a read- tradict of the product from end users Description: Category infort websites Brand: Aud Aler number / A20036020 Product: Products web found and measures were taken aliao in: Ireland Aler number / A20036020 Product: Product from end users Description: Category: Motor vehicles Brand: Aud Aler number / A20036020 Product: Product on web taken aliao in: Ireland Aler number / A20036020 Product: Product on web taken aliao in: Ireland Aler number / A20036020 Product: Spassager car Nume: OS Risk type: Injunes Category: Motor vehicles Brand: Aud Virge / number of model: Type-approval number: e1*200748*1550, Type: FY Type of aler: Products web taken aliao in: Ireland Aler number / A20036020 Product: Spassager car Nume: OS Risk type: Injunes Category: Motor vehicles Brand: Aud Virge / number of model: Type-approval number: e1*200748*1550, Type: FY Type of aler: Products web taken aliao in: Ireland Aler number / A20036020 Product: Spassager car Number / A20036020 Product: Spassager car Number / A20036020 Product: Products web found and measures aler homater / A2003602 Product: Products web found and measures web taken aliao in: Finland, Ireland Aler number / A20034120 Product: Products web found and measures were taken aliao in: Finland, Ireland Aler number / A20034120 Product: Products web found and measures web taken aliao in: Finland, Ireland Aler number / A20034120 Product: Products web found and measures web taken aliao in: Finland, Ireland Aler number / A20034120 Product: Products web found and measures web taken aliao in: Finland, Ireland Aler number / A20034120 Product: Products web found and measures web taken aliao in: Finland, Ireland Aler number / Alexades: IDDAB Aler number / Alexades: IDDAB Aler number / Alexad	
Name: Tigun Allipace Filts type: Injune Category, Motor welcles Strad: VW Type / number of model: Type-approval number: el '200 /118'0450', Type: NN Type / number / faccode: '202 Pacel and the model: Type-approval number: el '200 /118'0450', Type: NN Type / number / faccode: '202 Bach number / faccode: '20 Bach num	Alert number: A12/01339/20
Name: Tigun Allipace Filts type: Injune Category, Motor welcles Strad: VW Type / number of model: Type-approval number: el '200 /118'0450', Type: NN Type / number / faccode: '202 Pacel and the model: Type-approval number: el '200 /118'0450', Type: NN Type / number / faccode: '202 Bach number / faccode: '20 Bach num	
Category, Kotor vehicles Type / number of model: Type-approval number: e1 200 /110 0450°. Type: 5N Type / ander: Toolocit with aeious raise Due to a manufacturing error, the adjustment mechanism on the backwest traine of the first set and up to incorrectly webed. As a result, the stability of the set back and its restaining effect in the ovent of a rear-impact collision may be impaired, increasing the risk of Injury. / Real of the product from and users Description: Back number / Baccobe: 72KB NO Country of origin: Mexico And rushing error, the adjustment mechanism on the backwest traine of the first souther too you Read souther too you and measures were taken also in: heland And number. / BacTiol 2002 Product: Passenger car Nume: OS Risk type: Injurine Category. Motir vehicles Branc, Aud Type / number of model: Type-approval number: e1 * 2007/46 * 1550 . Type: FY Type of allet: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backwest traine of the front seat may be faulty or incorrectly webed. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Read of the product from end users Description: Batch number / Baccobe: 72L1 NO Country of origin: Mexico And the product with searses were taken also in: Finland, Instand And the module of the adjust commercial whicle Nume: Master Type / number of model: Type-approval number: e22007/46*0012*27, e2*2007/46*002*731, Type: MA, ML, VA Type of allet: Products with searces were taken also in: Finland, Instand Type / number of model: Type-approval number: e2*2007/46*0012*27, e2*2007/46*002*731, Type: MA, ML, VA Type of allet: Products with assons raise The earth connection in the trailer socks is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Type of allet: The optic the marker of the optic the marker adjust of the optic the marker of th	
Category, Kotor vehicles Type / number of model: Type-approval number: e1 200 /110 0450°. Type: 5N Type / ander: Toolocit with aeious raise Due to a manufacturing error, the adjustment mechanism on the backwest traine of the first set and up to incorrectly webed. As a result, the stability of the set back and its restaining effect in the ovent of a rear-impact collision may be impaired, increasing the risk of Injury. / Real of the product from and users Description: Back number / Baccobe: 72KB NO Country of origin: Mexico And rushing error, the adjustment mechanism on the backwest traine of the first souther too you Read souther too you and measures were taken also in: heland And number. / BacTiol 2002 Product: Passenger car Nume: OS Risk type: Injurine Category. Motir vehicles Branc, Aud Type / number of model: Type-approval number: e1 * 2007/46 * 1550 . Type: FY Type of allet: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backwest traine of the front seat may be faulty or incorrectly webed. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Read of the product from end users Description: Batch number / Baccobe: 72L1 NO Country of origin: Mexico And the product with searses were taken also in: Finland, Instand And the module of the adjust commercial whicle Nume: Master Type / number of model: Type-approval number: e22007/46*0012*27, e2*2007/46*002*731, Type: MA, ML, VA Type of allet: Products with searces were taken also in: Finland, Instand Type / number of model: Type-approval number: e2*2007/46*0012*27, e2*2007/46*002*731, Type: MA, ML, VA Type of allet: Products with assons raise The earth connection in the trailer socks is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Type of allet: The optic the marker of the optic the marker adjust of the optic the marker of th	
Bindie VW Type / Indie of Indie 1: Type-approval number: e1 2001/116/0450°, Type: 5N Type / Juliet / Products with aserous risks Due to a narufucturing error, the adjustment mechanism on the backnest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the ovent of a rear-impact collision may be impaired, increasing the risk of injury. / Resall of the product from end uses Description: Batch number / Baccole: 728/8 NO Country of origit: Mexico Alers submitted by: Germany Products were found and measures were taken also in: Ir leftand Aler number: A120134020 Product: Products were found and measures were taken also in: Ir leftand Alers number: A120134020 Products: Products were found and measures were taken also in: Ir leftand Alers number: A120134020 Products: Products were found and measures were taken also in: Fieland, Ir bears Type / Intuities Coaggery: Mator vehicles Type / Intuities Due to a manufucturing error, the adjustment mechanisms on the backwest frame of the front seat may be faulty or incorrectly welded. As a result, the abadity of the seat back and its seatsmit geflect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Products: were found and measures were taken also in: Finland, Ireland Alert number / Al201341/20 Product: Provement with Left to commercial webicle Name: Also Alers Commercial Name: Alers Com	
Type of later: Products with serious rake Due to an mutuckning seriou, te significanterin mechanism on the backwest frame of the front seat may be lauly or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of lighty. / Recall of the product from end users Description. Batch number / Barcode: 72/8 NO Country of ngis: Mexico Aler submitted by: Germany Products were found and measures were taken also in: Ireland Aler number: A1201340/20 Product: Passenger car Nome: Co. Batch number / Barcode: 72/8 NO Country of model: Type-approval number: e1 * 2007/45 * 1550 , Type: FY Type of anter of model: Type-approval number: e1 * 2007/45 * 1550 , Type: FY Type of aler: Products well series and its restraining effect in the event of a rear-impact collision may be linpaired, increasing the risk of lighty. / Recall of the producting error, the adjustment mechanism on the backwest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be linpaired, increasing the risk of lighty. / Recall of the product frame end users Description. Batch number / Barcode: 72.1 NO Country of ngis: Mexico Aler submitted by: Germany Products were found and the assures were taken also in: Finland, Ireland Aler number: Al201341/20 Product: Tron end users Description. Batch number / Barcode: 72.1 NO Country of ngis: Mexico Aler submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Aler number: Al201341/20 Product: Tron end users Description. Batch number / Barcode: 72.1 NO Country of ngis: Finland Aler submitted by: Germany Products were found and the series in alseguate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description. Batch number: Al201341/20 Product: Tron end users Description. Batch	• •
Type of later: Products with serious rake Due to an mutuckning seriou, te significanterin mechanism on the backwest frame of the front seat may be lauly or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of lighty. / Recall of the product from end users Description. Batch number / Barcode: 72/8 NO Country of ngis: Mexico Aler submitted by: Germany Products were found and measures were taken also in: Ireland Aler number: A1201340/20 Product: Passenger car Nome: Co. Batch number / Barcode: 72/8 NO Country of model: Type-approval number: e1 * 2007/45 * 1550 , Type: FY Type of anter of model: Type-approval number: e1 * 2007/45 * 1550 , Type: FY Type of aler: Products well series and its restraining effect in the event of a rear-impact collision may be linpaired, increasing the risk of lighty. / Recall of the producting error, the adjustment mechanism on the backwest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be linpaired, increasing the risk of lighty. / Recall of the product frame end users Description. Batch number / Barcode: 72.1 NO Country of ngis: Mexico Aler submitted by: Germany Products were found and the assures were taken also in: Finland, Ireland Aler number: Al201341/20 Product: Tron end users Description. Batch number / Barcode: 72.1 NO Country of ngis: Mexico Aler submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Aler number: Al201341/20 Product: Tron end users Description. Batch number / Barcode: 72.1 NO Country of ngis: Finland Aler submitted by: Germany Products were found and the series in alseguate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description. Batch number: Al201341/20 Product: Tron end users Description. Batch	Type / number of model: Type-approval number: e1*2001/116*0450*, Type: 5N
the stability of the seaf back and lis restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recail of the product from end users Description: Batch number / Barcole: 72/8 NO Courthy of orgin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Ireland Alert number: A1201340/20 Product: Passenger car Name: 0.5 Risk kpg: lighting Category: Motor vehicles Brand: Aud Type / number of model: Type-approval number: e1* 2007/46* 1550 , Type: FY Type of alert: Products were found and in restraining effect in the event of a rear-impact collision may be fauly or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be fauly or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recail of the products two the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recail of the products two the users Description: Back humber / Barcode: 72.1 NO Country of righ: Mexico Alert number: A1201341/20 Product: Products were taken also in: Finland, Ireland Mert number: A1201341/20 Product: Products two the seat back and and measures were taken also in: Finland, Ireland Erand: Remail Type / number of model: Type-approval number: c2*2007/46*016*35-38, e2*2007/46*0022*27, e2*2007/46*0477*31, Type: MA, ML, VA Type of alert: Products two the isolar scale Erand: Remail Mert submitted by: Germany Products two found and measures Back number / Barcode: DDAB NO Country of oright: France Alert submitted by: Germany Products two founds: Type-approval number: c2*2007/46*016*3-58, e2*2007/46*0022*27, e2*2007/46*0474*1074*1077, e1*2007/46*1074; e1*2007/46*1076, e1*2007/46*1076, e1*2007/46*1077, e1*2007/46*1077, e1*2007/46*1077, e1*2007/46*1077, e1*2007/46*1077, e1*2007/46*1077, e1*	
Recall of the product from end users Description: Batch number / Barcode: 72(9 NO Country of origin: Mexico Aler submitted by: Germany Products were found and measures were taken also in: Ireland Aler submitted by: Germany Products were found and measures were taken also in: Ireland Aler number / A120134020 Product: Pasenger ear Name: 05 Risk type: Injuries Category, Motor vehicles Danaf: Audi Type / number of model: Type approval number: e1 * 2007/46 * 1550 , Type: FY Type of alter: Treducts with section also Due to a manufacturing error, the adjustment mechanism on the backreat frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the set back and is restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product room end users Description: Batch mumber / Barcode: 721. NO Country of origin: Mexico No Country of origin: Mexico No Country of origin: Mexico No Country of origin: Mexico No Country of origin: Mexico Nator Earth and measures were taken also in: Finland, Ireland Aler submitter / Barcode: 721. NO Country of origin: Mexico No Country of origin: Parce No Country of origin: Frace No Country of origin: Germany No Country of origin: Germany No Country of origin: Frace No Country of origin: Germany No Count	Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result,
Description:" Batch number / Barcode: 72K9 NO Country of righ: Mexico Alert aubmitted by: Germany Products were found and measures were taken also in: Ireland Alert number. 12001340/20 Product: Passenger car Name: 0.5 Risk type: Irelands of the right o	the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. /
Bath number / Barcode: 72K8 NO Country of origin: Mexico Aker submitted by: Germany Products were found and measures were taken also in: Ireland Aker number / A20134020 Product: Passenger car Name: 05 Risk type: Injuries Category: More vehicles Band: Audi Type / number of model: Type-approval number: e1*2007/46*1550, Type: FY Type of anter: Products with serious risks Due to a manufacturing error. The adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat backr and fits seriarining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Does to barnes Aker submitted by: Germany Aker submitted by: Germany Product: Products: 7221 NO Country of arigin: Mexico NO Country of arigin: Mexico Category: Molor vehicles Bath number: A120134100 Product: Product and measures were taken also in: Finland, Ireland Aker submitted by: Germany Product: were found and measures were taken also in: Finland, Ireland Product: Products with services risks Category: Molor vehicles Bath number: A120134100 Product: Products with services risks Category: Molor vehicles Bath number: A120134100 Product: Products with services risks Category: Molor vehicles Bath number: A120134100 Product: Products with services risks Category: Molor vehicles Bath number: A120134120 Product: Products with services risks Category: Molor vehicles Bath number: A120134220 Product: Passenger car More: 2, S, F, R, 1, 2, 3, 3, S5 Risk type: Fite Category: Molor vehicles Brand: BW Type / number of model: Type-approval number: e1:2007/46*1824, e1:2007/46*1675, e1:2007/46*1676, e1:2007/46*1797, e1:2007/46*1618, e1:2007/46*1276, e1:2007/46*1674, e1:2007/46*1684, e1:2007/46*1676,	Recall of the product from end users
NO Courtry of orgin: Masica Alert automited by: Germany Products ware found and measures were taken also in: Ireland Alert number: A 120134020 Product: Passenger car Name: OS Tikk type: Ireland Catagory: Motor vehicles Eards number of model: Type-approval number: e1 * 2007/46 * 1550, Type: FY Type of number of model: Type-approval number: e1 * 2007/46 * 1550, Type: FY Type of number of model: Type-approval number: e1 * 2007/46 * 1550, Type: FY Type of number of model: Type-approval number: e1 * 2007/46 * 1550, Type: FY Type of number of model: Type-approval number: e1 * 2007/46 * 1550, Type: FY Type of number of model: Type-approval number: e1 * 2007/46 * 1550, Type: FY Type of number of her object from end users Description: Batch number / Barcode: 72.1 NO Country of origin: Masico Alert submited by Cermany Product: Passenger van / Ught commercial vehicle Name: Master Tikk type: Fre, Inpres Catagory: Motor vehicles Batch number / Al201341/20 Product: Passenger van / Ught commercial vehicle Name: Master Type of number / Orded: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of anter: Troducts thm and users Description: Batch number / Parcode: 0DAB No Country of origin: Pance Description: Batch number / Parcode: 0DAB No Country of origin: Pance Alert summited by: Germany Number / Al20134/2020 Product: Passenger car Name: 23, 5, 7rt, X1, X2, X3, X5 Hatk type: Figue approval numbers: e1*2007/46*1675, 81*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*20	Description:
Courtey of origin: Mexico Alers submitted by: Germany Products were found and measures were taken also in: Ireland Alers number: A120134020 Product: Passenger car Name: Os Category: Motor vehicles Brand, Aud Type / number: of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type of alers: Products with serious risks Due to a manufacturing arror, the algoistment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. J Reacial of the products threm end users Description: Batch number: Algoistat from end users Description: Batch number: Algoistat with sensus risks The earth connection in the trailer socket is indequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Fread of the product from end users Description: Batch number: Algoistat from end users Description: Batch number (barced: const fisso), Obt 560500 NO Construct of right: Germany Hit submitted by: Germany Hit submitted by: Germany Hit submitte	Batch number / Barcode: 72K8
Aler submitted by: Gernamy Produkts were found and measures were taken also in: Ireland Aler number. A1201340/20 Produkt: Passenger car Nume: OS Tisk type: Injuries Category: Motor vehicles Brand: Aud Type 7 number of model: Type-approval number: e1*2007/46*1550, Type: FY Type 0 atel: Produkts with serious risks Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. 7 Recal of the products with serious risks Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. 7 Recal of the product from end users Description: Alert number / Alarcode: 72L1 NO Country of origin: Mesico Alert number: A120134120 Product: Passenger van / Light commercial vehicle Name: Master Troid the product from end users Description: The earlt cornection in the tailer societ is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recaling is Motor vehicles Brand: Henault Type / number / Marcode: 10DAB NO Country of origin: France Alert number: A120134220 Product: Passenger car Name: A12013420 Product: Passenger car Name: A12013420 Product: Passenger car Name: A12013420 Product: Name car eath oring t	NO
Products were found and measures were taken also in: Freiand Aler number: A120134020 Product: Passenger car Name: 05 Rink Yppe: Injuries Category: Moro vehicles Brand: Aud De to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact onlision may be impaired, increasing the risk of injury. J Recall of the products throm end users Description: Batch number: Alr201341/20 Product: Passenger van / Lipht commercial vehicle Name: Master Products: Passenger van / Lipht commercial vehicle Name: Master Products: Passenger van / Lipht commercial vehicle Statist number: A1201341/20 Products: Passenger van / Lipht commercial vehicle Name: Master Products: Passenger van / Lipht commercial vehicle Statist number: A1201341/20 Products: Passenger van / Lipht commercial vehicle Name: Master Products: Passenger van / Lipht commercial vehicle Name: Master No Passengtion: Batch number / Barcode: 0DAB No No No No No No No No No No No No No	Country of origin: Mexico
Aler number: A1201340/20 Product: Passenger car Name: OS Rick type: injuries Category: Motor vehicles Brand: Aud Type / number of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type / antime to estatuse and the restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the products with senious risks Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72,1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Remault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*002*27, e2*2007/46*004*7*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the railer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire / Recator who for end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 76, X1, X2, X3, S5 Risk type: Fire Category: Motor vehicles Brand: Brund: Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1876, e1*2007/46*1876, e1*2007/46*1977, e1*2007/46*1987, type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1876, e1*2007/46*1876, e1*2007/46*1977, e1*2007/46*1987, type / number of model: Type-approval numbers: e1*2007/46*1825, e1*2007/46*1876, e1*2007/46*1876, e1*2007/46*1977, e1*2007/46*1987, type / number of model: Type-approval numbers: e1*2007/46*1826, e1*	Alert submitted by: Germany
Product: Passenger car Name: OS Risk type: Injuries Category: Motor vehicles Brand: Aud Type / number of model: Type-approval number: e1* 2007/46* 1s50, Type: FY Type of alter: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backreat frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72.1 NO Country of origin: Nexico Alter submitted by: Germany Products: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alter: Products with serious risks The earth connection in the tailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alter submited by: Germany Products: Resenger car Notor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alter: Products with serious risks The earth connection in the tailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alter submitted by: Germany Xiet submitted by: Germany Alter submitted	Products were found and measures were taken also in: Ireland
Product: Passenger car Name: OS Risk type: Injuries Category: Motor vehicles Brand: Aud Type / number of model: Type-approval number: e1* 2007/46* 1s50, Type: FY Type of alter: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backreat frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72.1 NO Country of origin: Nexico Alter submitted by: Germany Products: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alter: Products with serious risks The earth connection in the tailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alter submited by: Germany Products: Resenger car Notor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alter: Products with serious risks The earth connection in the tailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alter submitted by: Germany Xiet submitted by: Germany Alter submitted	
Name: 05 Rak type: injuries Gategory: Motor vehicles Brand: Audi Type / number of model: Type-approval number: e1*2007/46*1550, Type: FY Type / alert: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alors submitted by: Germany Product: were found and measures were taken also in: Finland, Ireland Alors submitted by: Germany Product: Basenger van / Light commercial vehicle Name: Alassier Risk type: Fin, Injuries Category: Motor vehicles Bard: Rumaber: A12/01341/20 Product: Pasenger van / Light commercial vehicle Name: Master Risk type: Fin, Injuries Category: Motor vehicles Bard: Rumaber Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alst:: Products with sectors also the earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Harcode: 0DAB NO Country of origin: France Alert submitted by: Germany Type / number of model: Type-approval numbers: e1*2007/46*1624, e1*2007/46*1676, e1*2007/46*1676, e1*2007/46*1677, e1*2007/46*1678, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*16188, Type / alert: Products files Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Mer 1. Also, S. Ter, X1, X2, X3, X5 Risk type: File Recall of the product from end users Product: Passenger car Neme: 2. S. 5. Ter, X1, X2, X3, X5 Risk type: File Recall of the product from end users Product from end users Description: Batch number / Barcode: 006154050	
Risk type: Injuries Gategory: Motor vehicles Brand: Audi Type / number of model: Type-approval number: e1* 2007/46*1550 , Type: FY Type / attent: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and fit restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Desoription: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fine, Injuries Gategory: Motor vehicles Brand: Brandt Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alse: Products twen berious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fite. / Recall of the product trom end users Description: Batch number / Barcode: ODAB NO Country of origin: France Alert number / A12/01342/20 Product: Rassenger can Name: 2, 3, 5, re, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Bmart / Barcode: ODAB No Country of ender: Type-approval numbers: e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1979, e1*2007/46*1918, e1*2007/46*076*1647, e1*2007/46*1947, e1*2007/46*1974, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1979, e1*2	•
Category: Motor vehicles Brand: Audi Type / number of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type / number of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type / number of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type / number of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type / number de acade and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72L1 NO Country of origin: Medico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Finak type: Fine, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2'2007/46'0016'35-38, e2'2007/46'0022'27, e2'2007/46'0047'31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the traiter socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number: A12/01342/20 Product: Passenger car Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Alert submitted by: Germany Alert number of model: Type-approval numbers: a1'2007/46'1675, e1'2007/46'1675, e1'2007/46'16776, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1917, e1'2007/46'1884, e1'2007/46'1675, e1'2007/46'1675, e1'2007/46'16776, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1917, e1'2007/46'1884, e1'2007/46'1675, e1'2007/46'1675, e1'2007/46'1797, e1'2007	
Brand: Audi Type / number of model: Type-approval number: e1 * 2007/46 * 1550 , Type: FY Type of alert: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and it is restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products Were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: ODAB NO Country of origin: France Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7, 4, 71, 22, 33, 25 Risk type: Fire Category: Motor vehicles Brand: Result by: Germany Alert number: A12/01342/20 Product: Ressenger car Name: 2, 3, 5, 7, 4, 71, 22, 33, 25 Risk type: Fire Category: Motor vehicles Brand: Barb number / Barcode: ODAB NO Category: Motor vehicles Brand: RW Type / number of model: Type-approval numbers: e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1676, e1*2007/46*16776, e	
Type / number of model: Type-approval number: e1* 2007/46* 1550 , Type: FY Type of alert: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backreast frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury, / Recall of the product from end users Description: Batch number / Barcode: 72.1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk bype: Fire, Injuries Category: Motry vehicles Brand: Fenault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the traiter socket is inadequate. This may lead to failure of the traiter's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number: A1201341/20 Product: Passenger car Name: 2, 3, 5, rx, XI, 2X, 3, X5 Risk type: Fire Category: Motor vehicles Brand: Remault Yupe / number: A1201341/20 Product: Passenger car Name: 2, 3, rx, XI, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Remault Yupe / number: A1201342/20 Product: Passenger car Name: 2, 3, rx, rX, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Remault Yupe / number: A1201341/20 Product: Passenger car Name: 2, a, rx, rX, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Remault Yupe / number: A1201341/20 Product: Passenger car Name: 2, a, rx, rX, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Remault Yupe / number: A1201342/20 Product: Passenger car Name: 2, a, rx, rX, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Remault Yupe / number: A1201347(*1074, e12007/46*1676, e1*2007/46*1676, e1*2007/46*1797,	• •
Type of alert: Products with serious risks Due to a manufacturing error, the adjustment mechanism on the backreat frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury, / Recall of the product from end users Description: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/0134120 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Baran: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product form end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918	
Due to a manufacturing error, the adjustment mechanism on the backrest frame of the front seat may be faulty or incorrectly welded. As a result, the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A120134120 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Benault Type / number of model: Type-approval number: e2'2007/46'0016'35-38, e2'2007/46'0022'27, e2'2007/46'0047'31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number: A1201342/20 Product: Passenger car Alert submitted by: Germany Alert number: 42, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type of alert: Troducts with serious risks The earth scance construction in the battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert number: 412/01342/20 Product: Resenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / anther of model: Type-approval numbers: e1*2007/46*184, e1*2007/46*1675, e1*200	
the stability of the seat back and its restraining effect in the event of a rear-impact collision may be impaired, increasing the risk of injury. / Recall of the product from end users Description: Batch number / Barcode: 72.1 NO Country of origin: Mexico Alert submitted by: Germany Products: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuras Category: Motor vehicles Brand: Renaul Type / number of model: Type-approval number: e2'2007/46'0016'35-38, e2'2007/46'0022'27, e2'2007/46'0047'31, Type: MA, ML, VA Type of alert: Products with estores risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: Frane Alert submitted by: Germany Alert number: A12/01542/20 Product: Passenger car Name: 2, 3, 5, ref, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Brand: Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: Frane Alert submitted by: Germany Alert number condel: Type-approval numbers: e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1276, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1276, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1947, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1947, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1947, e1'2007/46'1947, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1947, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'1947, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'	
Recall of the product from end users Description: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number: A12/0134/220 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Frand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1797, e1*2007/46*1797, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1797, e1*2007/46*1797, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*1047, e1*2007/46*1947, e1*2007/46*1648, Types: F2X, F2AT, F1X, G3X, G5X, TL, G3L, G3K, G5L Type of alert: Products time to users Description: Batch number / Barcode: 00AB NO Country of origin: France Alert submitted by: Germany Alert number: A12/0134/220 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1947, e1*2007/46*	
Description: Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Benault Type / number of model: Type-approval number: e2'2007/46'0016'35-38, e2'2007/46'0022'27, e2'2007/46'0047'31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trainer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 8, 5, For, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1977, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1920, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1977, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1920, e1'2007/46'1977, e1'2007/46'1978, e1'2007/46'	
Batch number / Barcode: 72L1 NO Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2'2007/46'0016'35-38, e2'2007/46'0022'27, e2'2007/46'0047'31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1824, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1047, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1047, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1047, e1'2007/46'1047, e1'2007/46'1047, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1047, e1'2007/46'1047, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1947, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1047, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1979, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1017, e	
NO Country of origin: Mexico Aret submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A1201341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 24, 35, 767, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: Benault 12007/46*1027, 61*2007/46*1947, e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1988, 12007/46*0276, e1*2007/46*1947, e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1988, 12007/46*0276, e1*2007/46*1947, e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1988, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*1978, e1*2007/46*0276, e1*2007/46*0276, e1*	·
Country of origin: Mexico Alert submitted by: Germany Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*2017, e1*2007/46*2017, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*1918, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*2017, e1*2007/46*2017, e1*2007/46*1918, e1*2007/46*2017, e1*2007/46*2017, e1*2007/46*1924, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*1918, e1*2007/46*1920, e1*2007/46*1920, e1*2007/46*1918, e1*2007/46*1920, e1*20	
Aleft submitted by: Germany Aleft submitted by: Germany Aleft number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of aleft: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Aleft number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, TL, G3L, G3K, G5L Type of aleft: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery. Increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Aleft submitted by: Germany	
Products were found and measures were taken also in: Finland, Ireland Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2'2007/46'0016'35-38, e2'2007/46'0022'27, e2'2007/46'0047'31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BWW Type / number of model: Type-approval numbers: e1'2007/46'1684, e1'2007/46'1675, e1'2007/46'1676, e1'2007/46'1797, e1'2007/46'1918, e1'2007/46'0276, e1'2007/46'1947, e1'2007/46'1047, e1'2007/46'1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, Lineraesing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	
Alert number: A12/01341/20 Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type / alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1017, e1*2007/46*1684, types: F2X, F2AT, F1X, G3X, G5X, TL, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery. increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany	
Product: Passenger van / Light commercial vehicle Name: Master Risk type: Fire, hjuries Category: Motor vehicles Brand: Renault Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: DDAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L. Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	
Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the bipt-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Alert number: A12/01341/20
Name: Master Risk type: Fire, Injuries Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the bipt-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Product: Passenger van / Light commercial vehicle
Category: Motor vehicles Brand: Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert submitted by: Germany Alert submitted by: Germany Type / number category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1027, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1945, many trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	
Bran <sup>1</sup> : Renault Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire, Injuries
Type / number of model: Type-approval number: e1*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Category: Motor vehicles
Type of alert: Products with serious risks The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1624, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Brand: Renault
The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*0217, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Type / number of model: Type-approval number: e2*2007/46*0016*35-38, e2*2007/46*0022*27, e2*2007/46*0047*31, Type: MA, ML, VA
Recall of the product from end users Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*104*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Type of alert: Products with serious risks
Description: Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*10217, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	The earth connection in the trailer socket is inadequate. This may lead to failure of the trailer's lighting devices and to increased risk of fire. /
Batch number / Barcode: 0DAB NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1624, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Recall of the product from end users
NO Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Description:
Country of origin: France Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Batch number / Barcode: 0DAB
Alert submitted by: Germany Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	NO
Alert number: A12/01342/20 Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Country of origin: France
Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Alert submitted by: Germany
Product: Passenger car Name: 2, 3, 5, 7er, X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	
Name: 2, 3, 5, 7e <sup>°</sup> , X1, X2, X3, X5 Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	
Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	•
Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Name: 2, 3, 5, 7er, X1, X2, X3, X5
Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	
Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire
e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles
Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW
A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918,
chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L
Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks
Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a
Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. /
NO Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users
Country of origin: Germany Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description:
Alert submitted by: Germany	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500
	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO
	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany
	Risk type: Fire Category: Motor vehicles Brand: BMW Type / number of model: Type-approval numbers: e1*2007/46*1824, e1*2007/46*1675, e1*2007/46*1676, e1*2007/46*1797, e1*2007/46*1918, e1*2007/46*0276, e1*2007/46*1947, e1*2007/46*2017, e1*2007/46*1688, Types: F2X, F2AT, F1X, G3X, G5X, 7L, G3L, G3K, G5L Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061540500, 0061560500 NO Country of origin: Germany Alert submitted by: Germany

Alert number: A12/01343/20 Product: Passenger car Name: Countryman Risk type: Fire Category: Motor vehicles Brand: MINI Type / number of model: Type-approval number: e1*2007/46*1682, Type: FMX Type of alert: Products with serious risks A short circuit in the high-voltage battery could occur during initial charging due to a particle in the form of a welding bead. This may trigger a chain reaction in the battery, increasing the risk of fire. / Recall of the product from end users Description: Batch number / Barcode: 0061530500, 0061550500 NO Country of origin: United Kingdom Alert submitted by: Germany Products were found and measures were taken also in: Poland
Alert number: A12/01348/20 Product: Bus Name: I6, Scaia Citywide, Scania Higer Risk type: Injuries Category: Motor vehicles Brand: Scania Type / number of model: Models: e9*2007/46*0437*79, e9*2007/46*8038*00, e4*2007/46*0055*40+42, e5*2007/46*1200*02, Type-approval numbers: i6CD3-SCN-M330, i6CD2-SCA-M320, M323,Scania Higer A-series Type of alert: Products with serious risks Defective gas pressure regulators cause the tank to crack. If the gas tank cranks, persons in the near area could be injured due to the high internal pressure of the tank. / Recall of the product from end users Description: Bus Batch number / Barcode: RC 200312 NO Country of origin: Sweden Alert submitted by: Germany
Alert number: A12/01322/20 Product: Plastic ball Mame: Sport toys Baby Ball Risk type: Chemical Category: Toys Brand: Ya Hong Type / number of model: 118239 Type of alert: Products with serious risks The plastic material of the ball contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 27.4% by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation. Withdrawal of the product from the market Description: Baby Ball - Colored inflatable ball with a diameter of 22 cm with pictures (e.g., a picture of a star / fruits / animals). Batch number / Barcode: 8590331182398 UNKNOWN Country of origin: People's Republic of China Alert submitted by: Czechia For submitted by: Czechia

Alert number: A12/01323/20 Product: Plastic doll Name: L. O L. SURPRISE Risk type: Chemical Category: Toys Brand: HAPPY PARTNER! Type / number of model: N. LQ-6 Type of alert: Products with serious risks The plastic material of the doll contains bis

The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 20.7 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation. Withdrawal of the product from the market

Description: Plastic doll (Other inscriptions: "LIL SISTERS, CHARM IS INFINITE, FASHION"), high 15cm - different dress and colored plastic hair, white shoes. 3+.

Batch number / Barcode: 8618000022018 UNKNOWN

Country of origin: People's Republic of China Alert submitted by: Czechia





Alert number: A12/01324/20 Product: Plastic doll Name: Beauty MAGIC FAIRY Risk type: Chemical Category: Toys Brand: Type / number of model: Type of alert: Products with serious risks

The plastic material of the doll contains bis (2-ethylhexyl) phthalate (DEHP) (measured value: 13.2 % by weight). This phthalate may harm the health of children, causing possible damage to the reproductive system. / The product does not comply with the REACH Regulation. Withdrawal of the product from the market

Description: Plastic doll (about 16cm tall) a fairy with multicolored butterfly plastic wings.

Batch number / Barcode: 8597521000197

## UNKNOWN

Country of origin: People's Republic of China Alert submitted by: Czechia



Alert number: A12/01325/20 Product: Baby doll pull-along toy Name: Flash Baby Risk type: Choking Category: Toys Brand:

Type / number of model: REF Nr. 1026

Type of alert: Products with serious risks

Small parts such as one of the wheels can easily detach. A small child may put them in the mouth and choke on them. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1

Withdrawal of the product from the market

Description: Plastic doll with 3 wheels that moves by means of cord retraction and its nappy pants flash. Batteries are not replaceable. It is sold together with 1 little bag with sugar tablets.

Batch number / Barcode: 6920017101085 UNKNOWN

Country of origin: People's Republic of China Alert submitted by: Austria



Alert number: A12/01329/20 Product: Key ring with a soft toy Name: Risk type: Choking Category: Toys Brand: TEDi Type / number of model: 7604900228 Type of alert: Products with serious risks The metal ring can easily detach from the toy becoming a small part. A small child may put it in the mouth and choke on it. / The product does not comply with the requirements of the Toy Safety Directive and the European Standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market Description: Key ring with a soft toy in the shape of a cow. Batch number / Barcode: 76049002281000000150 UNKNOWN Country of origin: People's Republic of China Alert submitted by: Slovakia

The control of the co



Alert number: A12/01330/20 Product: Toy Slime Name: Barrel-o-Slime Risk type: Chemical Category: Toys Brand: ADAR Type / number of model: Item N0. A108101 Type of alert: Products with serious risks The migration of boron from the toy slime is too high (measured value up to: 880 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging their reproductive system. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3. Destruction of the product, Withdrawal of the product from the market

Company recall page: http://www.adar.com.pl/index.php?p=komunikaty (http://www.adar.com.pl/index.php?p=komunikaty)

Description: Toy slime available in different colours. Batch number / Barcode: 5901271415645

(D

UNKNOWN

Country of origin: People's Republic of China Alert submitted by: Poland



Alert number: A12/01332/20 Product: Toy slime Name: Barrel-O-Slime Risk type: Chemical Category: Toys Brand: Type / number of model: 00311786 Type of alert: Products with serious risks The migration of boron from the toy slime is too high (measured value up to 3450 mg/kg). Ingestion of or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-3. Recall of the product from end users, Withdrawal of the product from the market Description: Colourless slime. Batch number / Barcode: 8592190117863 UNKNOWN Country of origin: People's Republic of China Alert submitted by: Slovakia **DITUA**3

00311786

Sliz/Umota Sliz/Umota



Alert number: A12/01335/20 Product: Battery Operated Toy Name: Flashing Christmas Bracelets Risk type: Chemical, Injuries Category: Toys Brand: Baker Ross Type / number of model: AV636 Type of alert: Products with serious risks The electrical circuit and the button batteries can easily detach from the toy. A child could place any of them in the mouth and choke on it. When swallowed, button cells can trigger the generation of the highly corrosive sodium hydroxide in the body, leading to severe burns and tissue damage. / The product does not comply with the requirements of the Toy Safety Directiv and the relevant European standard EN 62115. Recall of the product from end users Description: Flashing Christmas bracelets Batch number / Barcode: 50501174078239 NO Country of origin: United Kingdom Alert submitted by: United Kingdom C: 88



Alert number: A12/01345/20 Product: Flashing Swing Ball Name: Fun Toys Flashing Swing Balls Risk type: Strangulation Category: Toys Brand: Baker Ross Type / number of model: EF453 Type of alert: Products with serious risks Given the design and the material of the toy, a child could swing the toy around the head and twist it around the neck, causing strangulation. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1 Recall of the product from end users Description: Soft squishy light up balls Batch number / Barcode: 5051174046573 NO Country of origin: United Kingdom Alert submitted by: United Kingdom





Alert number: A12/01346/20 Product: Flashing Toy Name: Funky Faces Flashing Rings Risk type: Chemical, Injuries Category: Toys Brand: Baker Ross Type / number of model: AR472 Type of alert: Products with serious risks The electrical circuit and the button batteries can easily detach from the toy. A child could place any of them in the mouth and choke on it. When swallowed, button cells can trigger the generation of the highly corrosive sodium hydroxide in the body, leading to severe burns and tissue damage. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 62115. Recall of the product from end users Description: Flashing children's rings

Batch number / Barcode:

NO

Country of origin: United Kingdom Alert submitted by: United Kingdom





Alert number: A12/01328/20 Product: LED Bulb Name: LED Music Bulb Risk type: Electric shock Category: Electrical appliances and equipment Brand: Type / number of model:

Type of alert: Products with serious risks

The speaker cover can easily be twisted off exposing live parts. A user may touch them and receive an electric shock. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60598-1.

Recall of the product from end users, Removal of this product listing by the online marketplace

Description: Wireless bluetooth LED bulb with remote controller. The product was sold online, in particular via Wish.com. Batch number / Barcode:

NO

Country of origin: People's Republic of China Alert submitted by: United Kingdom



Alert number: A12/01331/20 Product: Nail dust collector Name: Nail Dust Collector Risk type: Burns, Fire Category: Electrical appliances and equipment Brand: Type / number of model: 858-5 Type of alert: Products with serious risks The clearance/creepage distances between the mains input circuits and low voltage output circuits are not sufficient. This may lead the cord to catch fire, causing burns to the user. / The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335-1.

Destruction of the product

Description: A white appliance with 3 fans to collect dust from nails with plastic covering.

Batch number / Barcode:

UNKNOWN

Country of origin: Hong Kong

Alert submitted by: United Kingdom



Alert number: A11/00079/20 Product: Keychain Name: Risk type: Choking, Injuries Category: Toys Brand: Shimmeez Type / number of model: PA Reg N. 18699 (CN), F/YK052019, SMZ01000 Type of alert: Products with other risk levels The sequins can easily be detached. A small child might put the toy in the mouth, detach the sequins with the teeth and inhale them. This could lead to infection in the lungs. Moreover, the fibrous stuffing material is easily accessible due to the weakness of certain seams. A small child may put the stuffing material in the mouth and choke. / The product does not comply with the requirements of the Toy Safety Directive and the relevant European Standard EN 71-1. Recall of the product from end users, Withdrawal of the product from the market Description: A stuffed animal keychain with sequins and a plastic carabiner. Batch number / Barcode: 603154010521 UNKNOWN Country of origin: People's Republic of China Alert submitted by: Slovakia

