

| Safety Gate : the EU | rapid alert system | for dangerous non-foo | d products | | | | | | | | | | | | | | | | | | | | | | |
|--|--------------------|-----------------------|---|-------------------------------|-------------|--------------|--|--------------------|---|--|---------|---------------------------------------|------------------------|---|---|--|---|---|--|---|----------------------|--------------|---------------------|---------------------------------------|--|
| (**) Please note that Type of alert | Type | Alert number | Alert submitted by | Country of origin | Counterfeit | Risk type | Risk legal provision | Product | Name | Description | Brand | Category | Type / number of model | OECD Portal category | Risk | Compulsory measures | Voluntary measures | Products were found and measures were taken also in | Company recall pag | e URL of Case | Barcode | Batch number | Company recall code | Production dates (**) Packa descri | aging ription |
| Serious risk | Consumer | \$8,922989,25 | France | People's Republic of China | 500 | | The product does not comply with the comply with the requirements of the The requirements of the T | Soft toy | Peluche husky | Soft toy in the form of a day (Pushy) with first in the body and doubt stuffing sin the body and doubt stuffing soft of the lower part of the toy's body (lower belly). | GAUSAPA | Toys | 31048 | 86000000 - Toys / Garnes | Sentil parts can easily elastach (eyes of last). A child could put it in its mouth and choke. | | Type of economic operator taking notified measure(s): Importe measure(s): Importe product from the market product from the market Date of entry into force: 25/04/2025 Type of economic operator taking notified measure(s): Importer Category of measure(s): Importer Category of measure(s): Type of economic operator taking notified from end users Date of entry into force: 25/04/2025 | | hates (Flagment commany street) with (Flagment commany street) and | ustess // Zie europa auch strip gete- sient/screen/watelege zient/screen/watelege zient/screen/watelege | £ 564282000362 | CP00000834 | | | ckaging |
| Serious risk | Consumer | \$4/03003/25 | United Eingdom in respect of Northern Iveland | People's Republic of China | Uminowen | | The product does not comply with the comply with the requirements of the Machinery Directive. | Electric chainsiaw | Power 2 Juch Mini Battery Diectric Chainsaw | Red 12-inch chain saw with plastic blade cover. | | Machinery | TZ-C03AE | 83000000 - Tools / Equipment - power | Due to poor quality of the internal solution grant the inchema location grant the inadequate creepage and the inadequate creepage and cancer distances within the chappy, the user could have access to live parts and receive, the user as electric shock. Moreover, so the product tacks a manual activated chain brake, if the product tacks have accessed chain prake, the corn me foliate control of the chainsaw, and be injured. | y y | Type of economic operator taking notified measure(s): Importe measure(s): Importe occupant of measure(s): Importe operator taking notified perioduct Date of entry into force: 21/01/2025 | | | https://ex.auropa.au/s- try-gate- siarsisiscreen/washigeo 1/akertba.sai/10095669 | 4 | | | Brown packag | cardboard |
| Serious risk | Consumer | \$4,02993,25 | France | People's Republic of China | No | | The product does not comply with the comply with the requirement of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-15. | Rice cooker | Sushi party | Rice cooker and such in making accessions. All batches are affected. | BAANOT | Eactrical aggliances and equipment | | 2600000 - Electrica Supplies | underneath the handle of the appliance reachet too high temperatures. The user may inadevertently touch this surface dering use, resulting in burns. Additionally, the creepage distances for the main inculation are insufficient. This may lead to the user receiving an electric shock. | | Type of economic operator taking notified macure(s). Imported macure(s). Imported macure(s). Recall of the product from end users Date of entry into force: 01/07/2025 | | https://tappeal.como.go 4.1ffcha- rappel/13634/interne | ubites / Fis evenous en lui vir pate. Hersty pate. Hersty (rene) wustkappen triekertbesel / 10095263 | £ 0660767953314 | | | | |
| Serious risk | Consumer | SAV0298S/25 | подиту | People's Republic of China | Contin Down | | The product does not comply with the comply with the comply with the requirements of the Low Voltage Directive nor with the European standard EN 60098. | Lighting chain | | Lightning chair with 100 warm white colour class controlled LEDs, green wives, a controlling box unit, and outlet. | Yedo | Lighting chains | 100LED | 76000000 - Evetrica Supplies | archered finessing clobal rat the accessible were have inadequate insulation. Moreover, the product, most protected against moisture although it is recommended to undoor use. The water could penetrate the product or the use could penetrate the product or the use and the could be parts and receive an electric shock. | measure(s) were ordered: Distributor Category of measure(s): (withdrawal of the product from the market Distributor Category of measure(s): (withdrawal of the product from the market Distributor Category of measure(s): Type of economic operator to whom the measure(s) were ordered: Distributor Category of measure(s): Recall of the product from end users: Date of entry into force: (27/05/2025 | | | | https://ex.europa.eu/u r/v.path. Jates/s/crepn/webboo L/Jates/bergal/10045172 | d 6426485447477 | | | | rful cardboard box. |
| Serious roik | Consumer | SAV02984/25 | nogery | People's Republic of China | lanin power | Betric shock | The product does not comply with the comply with the requirement of the Low Ordrage directives nor with the European authorized the Coopean Cashed CTV 60098 | Lighting chain | Lampki Cholekowa LED | Ughting chain consisting of 100 LEDs, flashing unit, IVA4 marking, a flat pring and a flat and staceable societ. | | Lighting chains | 100WW | 78000000 - Electrica Supplies | plugs and the dimensions of the connection plug are incorrect. The product is not protected against moisture although it is recommended for | Type of sconnenic operator to whom the properties of the product and single properties of the product and single product of entry into force 03/04/2025 Type of accompanying measure of the product of entry into force 03/04/2025 Type of accompanying measure of the product of the product of entry into force 03/04/2025 Bacail of the product from end users of the product of the produ | | | | https://www.nps.au/n skr.gatia. alers/s.croon/waldene V/alertDetail/10095378 | # 8401501103016 4 | | | Colour | The state of the s |



| Serious risk | Consumer | 58/02990/25 | Germany | People's Republic of China | Unknown | Sectric shock | comply with the requirements of the tow Votage Directive nor with the European carniard fiv 6296-1. | | USB C Nattelli S Poet mit Schalter, GaP PD M 45W Laptop Port, Geffecht Kabel | won-54 w/n high products in south with a september is south with a september is settle. Product sold confine, in particular via Amazon (ASN: 80D72PYTG4). | Wolse | Electrical appliances and wquipment | | 7800000 - Electrical Gugafies | | Upon of accommon. Synoprison to whom the measure(s) were Chapter of the accommon. Chapter of the Chapter o | Street, file de manue anchet de la date de la date de la composition de la composition de planticion (2009-83) | 3 | Platfor Say in a carefood with a carefood so the carefood so |
|---------------|----------|--------------|---------|-------------------------------|---------|---------------|--|---------------|---|---|------------------------|--|--|----------------------------------|---|--|---|--|--|
| Serious risk | Consumer | SN/CQ2935/25 | France | France | No | Proc. | The product does not comply with the Regulation on the approval and market surveillance of motor whicks and the whicks and the trailers, and of system components and separate technical units intended for such whicks. | Passenger car | C3 Aircross V3, C3 V5, V3, C4X, C3 Aircross, C Aircross V2, C3X, Basal | | CITROEN | | 42*200/46*0642*20- **24 CS Airross, 42*200/46*0035*01- **25 CS Airross, 42*20035*06*01- **25 CS Airross, 42*20035*06*00 **25 CS Airross, 42*20035*06*00 **25 Airross, 42*20035*06*00 **25 CS Airross, 42*20035*06*00 **25 CS Airross, 42*20035*06*00 **27 CS KS, 48*2007/46*5815*20- **27 CS KS, 48*2007/46*5815*20- **27 CS KS, 48*2007/46*5815*20- **27 CS KS, 48*20035*20*00 **25 CS Airross, 42*20035*20*00 **25 CS Airross, 42*20*00 **25 CS Airro | 77000000 - Automotive | The whicker may have a fuel bask in the high-persource hore, between the high-pressure and the high-persource may be an another than the high-persource may be a full because of loose nuts. This required the high-person of | Type of economic proposal entering in the control taking entitled in the control taking entitled in the control taking entitled in the control taking and the product in the control taking and the product in the control taking and the product in the control taking and entering and entering in factors and entering in factors and entering in factors and entering and ent | Stitler, Life and recommendant that affects and the state of the state | 666 11.1.2022 7.2.4.2005 CS ANOME STATE OF THE PROPERTY OF THE | |
| Serious risk | Consumer | SR/02930/25 | France | France | No | Fine | The product does not comply with the kagulation on the approval and market surveillance of motor whicles and their trailers, and of systems, components and separate technical units intended for such whicles. | Passenger car | DS3 Crossback, DS4 V2 | | DS automobiles | Motor vehicles | 2*72007/46*0628*31- *35 D54 V2, e2*2007/46*0639*22- *23 D53 Crossback, e2*2007/46*0639*25- *37 D53 Crossback, g11*2018/854*0060*0 0 D53 Crossback | 77000000 - Automotive | The vehicle may have a fuel leak in the high- pressure hose, between the high-pressure pump and the rail, because of loose nuts. This may cause a fire in the vehicle. | Figure of exconnects along models of commany. Contails, separate taking resident dealing resident taking resident dealing res | https://oc.europa.au/ai/ stre.gata: airent/screen/wobflagor t/airentbatai/10009422 | 696 13.3.2024 - 22.4.2025 54-V2 \$1.1.2022 - 17.4.2025 553 Crossback | |
| Serious risk | Consumer | SN/02936/2S | France | France | No | Free | The product does not comply with the the Regulation on the Regulation on the Regulation on the supproval and market surveillance of motor whicks and the whicks and their brailers, and of systems, corresponds and with the survey of the surve | Passanger car | 268 V.2. 369 V.3. 406 2008 V.2. 3506 V.2. 3506 V.3. V.3. 5008 V.2. 5008 V.3 | | Pougeot | Motor vehicles | #17007/46*054*75- *77 1008 V. #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*054*75- #71007/46*0554*70- # | 77000000 - Automotive | The whicks may have a find take in the hip- pressure hose, between the high-pressure may be and the rail, bicause of loose rust. This may cause a fire in the vehicle. | Type of economics generated to the product to taking reduction to the product to taking reduction to the product to taking reduction to the product to the product of the product of the product to the product to the product of entry rim force 14,007,005 m force | Person Africa accessor socialed the person of the person | MGZ 21.1.4.2032 7.2.4.2035 200 200 200 200 200 200 200 200 200 20 | |
| an 100 a 100. | | 34,0033423 | | | | | The product does not comply with the Regulation on the approval and market surveillance of motor veib fices and their trailers, and of systems, components and separate berhincia units intended for such websicles | | Astra L, Consa, Fronter Grandland X, Grandlan V2, Molška | | Copact Water Committee | | *31 Grandland X, e2*2007/46*0628*28*36 345 Astra 1, e2*2007/46*0639*21*35 Mokia, e2*2007/46*0639*26*35 Coria, e2*2007/46*0639*28*37 Mokia, e2*2003/46*0639*28*27003/46*0639*28*27003/4585*00054*04*07 070 Grandland V2, g11*2018/858*00054*04*04*07 Grandland V2, e11*2018/858*00054*04*01*36*27 | 700000 - AUJUNIONE | fuel leak in the high- pressure hose, between the high-pressure pump and the rail, because of loose nuts. This may cause a fire in the vehicle. | operator taking rotified levelund, (Lourellander), International (Lourellander), Catagory of measurable). Road of the product from end loans the loan of the loans the loans of the loans the loans | ore paties, alaran Aucesson I west Magazin Chale et Chestal I 100096-875 | Autora L 212,2003-22-4,005 Corea 213,244-34-2,025 307,2004-34-2,025 Fronters 4,11,202-27-4,205 4,2,2023-8,11,2004 Grandland X | |
| Serious risk | Consumer | SR/02931/25 | France | France | No | fire | The product doss not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate berknical units intended for such vehicles. | Passenger car | Avenger | Passenger car. | Jacp | Motor vuhicles | 63*1018/858*00078*06 63*1018/858*00078*06 63*1018/858*00078*07 63*2018/858*00078*07 63*2018/858*00078*11 63*2018/858*00078*12 63*2018/858*00078*13 | | The vehicle may have a fuel leak in the high- pressure hose, between the high-pressure pump and the rail, because of loose nuts. This may cause a fire in the vehicle. | Type of accordanic special to the special special behavior of the special special special behavior of the special spec | https://fice.acmene.achied this paths: activity/cocon/withhappor Dates (Spatha) (1995-6-25) | 16.1.1034 - 17.5.2025 | |
| Serious risk | Consumer | SR/02934/25 | France | France | No | Fire | the product does not comply with the hagulation on the approval and market surveillance of motor web/cles and their trailers, and of systems, components and separate technical units intended for such web/cles | Passenger car | 600, Grande Panda | Passenger car. | Fiat | Motor vuhicles | e2*2018/858*00035*08 (Grande Panda), e3*2018/858*00078*05 *06 (600), e3*2018/858*00078*12 (600) | 77000000 - Automotive | The vehicle may have a fuel leak in the high-pressure hose, between the high-pressure pump and the rail, because of loose nuts. This may cause a fire in the vehicle. | Payer of accomment properties of the comments (Cantala, posterior taking conflict, came microury, Storenia femanisme), and conflict tame microury, Storenia femanisme, and conflict tame microury, and conflict tame m | notes ul fue europa anul sal es pugate. All en fue partie. All en fue con fue si his por si del en fue sal d'i 10095-62 2 | F511 92.205-78.4205 facedo Predigi 92.2024-175.2025 fs000 175.2024-175.2025 fs000 183.3004-22.41025 | |
| Serious risk | Consumer | SR/02929/25 | France | France | No | Sire | The product does not comply with the Regulation on the approval and market surveillance of motor web/cles and their trailers, and of systems, components and separate technical units intended for such web/cles | Passenger car | Ypsilon | Passenger car. | Lancia | Motor vehicles | e2*7007/46*0639*31- *37 | 77000000 - Automotive | The vehicle may have a fuel leak in the high- pressure hore, between the high-pressure pump and the rail, because of toose nuts. This may cause a fire in the vehicle. | Type of economic popular to taking rediffered to ta | https://ec.auropa.au/se/ ety-gathe: alacts/scoren/handlepox (Jalenthota al./10095429) | 18.3.2034 - 22.4.2025 | |



| | | | | | | | | | | | e3*2018/858*00078*0 | | | | | | | 4 - 22.4.2025 |
|--------------|--------------|-------------|--|---------------------------|--|--|--------------------|--|---|---------------------------------------|--|--|--|--|--|--------|-----------------|-----------------|
| Serious risk | Consumer | 58/02933/25 | France | France No. | Fire | The product does not comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such wehicles | Passenger car | Junior Passenga | ar. Alfa Romeo | o Motor witricles | 63*2013/658*00078*0 63*2018/658*00078*1 *13 | 1 | The vehicle may have a fuel leak in the high-pressure hose, between the high-pressure pump and the rail, because of loose russ. This may cause a fire in the vehicle. | Type of accommonic special real register for the commonic special real register for the common register for the common register for the common register for the common register for the commonic for the common register for t | https://ex.europa.mu/ud Measalais Alert V.croson/europa. V.riiert Datum/ 20095432 | | F51N 11.7.20 | 4 - 22 4 2005 |
| Serious risk | Professional | SR/02948/25 | Cyprus | Unknown Uni | Rhown Electric shock | The product does not comply with the requirements of the Machinery Directive. | Power generator | Gasoline generator Red ports generator generator metalic for sold online via skrout grbazaar. | ie powier YAOHU na black mei. Product in particular gr and | Machinery | YH3800D | 82000000 - Tools / Equipment - power | The product lacks the required documentation, markings and conformit assessment. Therefore, the product may not be used properly with the risk of users receiving an electric shock. | Type of examinists Type of examinists massacre(s) were quotient importer Category of messure(s) mount reporter tamper r | http://je.aumoba.aufuid eth-public dernings. derningson/aumblagor Lidentibatail/10094427 | | | Cardboard box. |
| Serious risk | Professional | SR/02969/25 | Germany | Austria No | to jurida s | The product does not comply with the flegulation on the approval and market surveillance of agricultural and forestry vehicles. | Tractor | Puma, Maocum, Farmall, Agricultur Quantum | | Motor vahicles | D2, D5, DH, LF, L2, LU, 14, A2, A8, A6, 24*167/2013*00458* 624*167/2013*00458* 68*167/2013*0058* 613*167/2013*00218* 68*167/2013*00211* 624*167/2013*0030* 613*167/2013*0030* 613*167/2013*0031* 624*167/2013*0031* 613*167/2013*0031* | | Mechanical components of the parking brake (the teeth of the ratchet) wear out unusually quickly, leading to a loss of function. The vehicle may roll away unintentionally. This causes a risk of injury. | Figure of economic Sciences of the contract training confidence of the contract training confidence of the contract training confidence of the contract of the product of the product of the product of the contract of the product of the contract of the con | ettps://ec.auropa.au/hid sta.gatta auroshinenen/austingor Salentbarall/1909946.2 | | | 11 - 31/07/2022 |
| Serious risk | Professional | SA/02973/25 | Germany | Austria No | injuries | The product does not comply with the Bagulation on the approval and market surveillance of agricultural and forestry wehicles. | Tractor | 74, Powerstar 74, 15, 16, Agricultus vehicle | NEW HOLLA | Mator vehicles | \$37-967/0031-902/24- \$15.04.16.00, 500, 104.16.16.00, 104.16.16.16.16.16.16.16.16.16.16.16.16.16. | | Mechanical components of the parting braise (the tested of the ratched) wear out unusually wear out unusually quickly, leading to a loss of function. The vehicle may roll away unintentionally. This causes a risk of injury. | Fee of economic Sciences operated taking confidence of the season(s) Other Control Con | States of the control and the | | MM/925 1.4.3022 | -31.7.2002 |
| Serious risk | Professional | SR/02968/25 | Germany | Austria No | o juries | The product does not comply with the flegulation on the approval and market surveillance of agricultural and forestry wehicles. | Tractor | Kompakt, Profi Agricultur wehicle | and forestry STEYR | Motor vehicles | e24*167/2013*00369* e13*167/2013*00699* DJ, LG, L3, A3, e*167/2013*00072*, e13*167/2013*00072*, e13*167/2013*00321* e13*167/2013*00275* | | Mechanical components of the parking brake (the teeth of the ratchet) wear out unusually quickly, leading to a loss of function. The vehicle may roll away unintentionally. This causes a risk of injury. | Type of Sectoratic operator Laking modified measure(s): Other Clargery of measure(s): those and users. Date of entry into Serces Usersowan Laking and Users Usersowan Laking and Usersowan Laking and Users Usersowan Laking and Usersowan Laking and Usersow | integri/fee.auropa.au/hal try-gatte: sterss/noreen/nexhibiteor s/alert/Detai/1.0005465 | | CA0925 01.04.21 | 21 - 31.07.2022 |
| Serious risk | Consumer | SH/02967/25 | Hungary | Ontreed Arab Emirates Con | Osemul | The product does not comply with the Committe Products Meguliation. | Parfuma | | Oud Al Arab | b (Coveredos | | | (BMHCA), which is prohibited in cosmetic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | the product and tray more beautiful and the product of the product | Section of the section and well of the section of t | 04/062 | | Combined thes. |
| Serious risk | Consumer | sw/08002/25 | United Kingdom in regisect of Northern Invaled Nor | People's Republic of Con | Omensed, Challeng, Strong allering Strong allering Strong | This product does not comply with the comply with the comply with the year, and the year, and the year of the Toy Safety Directive. | Activity toy board | Chaldwar's Buny Research Woodson Harmonia | ng a clock ands, a with buttons, get spinner ny operated | Toys | 1798005 | ascoccoo - Toys / Games | accessible. A child may put them in the mouth and swallow them, which could cause damage to the child's gastroinestinal tract and/or chaiking astroinestinal tract and/or chaiking. Additionally, the rope at the top and could used it secure the phone toy to the board is too long an could targle around the child's neck causing strangulation. | Type of accurate in a constraint or when the measure(s) were extracted to when the measure(s) were extracted inspiration (s) and the constraint (s) and the cons | Stitute (fine entresis accident fine acciden | | | |
| Serious risk | Consumer | SR/02946/25 | United Kingdom in respect of Northern Ir eland | Germany No | Choking | The product does not comply with the requirements of the Toy Safety Directive. | Toy tree | Montessori Sound Tree Wooden thape of detachable flavers an which ca the top or move across the creating stold ceiling via Timy I in Time I in Tin | wooden ismall balls se placed at he tree to eaws, and Product in particular nible. | ie Toys | | 86000000 - Toys / Games | The product has small parts (plastic balls). A small child may put them in their mouth and choke. | Fyre of decomment sport and the table of the measure(s) Manufacturer Canager of measure(s) the state that the Date of entiry into force: \$8,077,2025 | ettys //ec. auropa au/sul ets attis altertiverson/authlepe (hiertiveral/100996)] | | | |
| Serious risk | Consumer | SR/02951/25 | United Kingdom in respect of Northern Ireland | Un known Un | Suffication | The product does not comply with the General Product Safety Regulation. | Baby sleeping bag | Baby Kintted Sleeping White kin Swaddle Bed sold engline in the sold cells via teenyl | ed sleeping ies. Product in particular mps. co.uk | Childcare article children's equip | and eers | 7500000 - Household / Office furniture / Furnishings | The sleeping bag has a hood, which may cover the mouth and/or note area of the baby. This could lead the child to suffocate. | Figure of economics operator training notified measure(s). Other Category of measure(s): World-color of the product from the market post of the property of the category of the 13406/2023. | https://ec.aucroba.auchid sha.ailia: ahert-lucean/webhapor LakertDerail/10095055 | | | |



| | | | | | T | | | | | | | | | | | | | | | | | | | | |
|-------------------|--------------|-------------|---|-------------------------------|---------|----------------|--|-------------------------|-------------------------------------|--|------------|---------------------------------------|---|----------------------------------|--|--|---|--------|--|--|--------------|-----|---------|------------------------|-------------------------------------|
| Serious risk | Consumer | SR/02953/25 | Germany | People's Republic of China | Unknown | Injuriës | The product does not comply with the Personal Protective Equipment Regulation. | Bicycle helmet | | Black bicycle helmet. Product sold online, in particular via Shein. | | Hobby/sports equipment | LS-TK-01-07 | 7100000 - Sports equipment | The shock-absorbing capacity of the helmet insufficient. As a result, the user might suffer injuries in case of an impact. | is | Type of economic operator taking notified measure(s): Other Category of measure(s): Removal of this product fisting by the online marketplace Date of entry into force: 29/08/2025 | | | https://ec.europa.au/sal str-pate. salests/screen/webilepor t/alertDetail/10095511 | | | | | |
| Serious risk | Consumer | 58/02927/25 | United Engdom in respect of Northern Ivaliand | People's Republic of China | Unknown | Electric shock | This product does not comply with the magazinements of the Low voltage Directive. | Rotating digitary stand | | Electric rotating display base stand with remote control. Product control. | Baoshidhan | Electrical appliances an equipment | | 78000000 - Electrica Supplies | The product has insidequate insulation, which makes two parts accessible. The user could book the accessible the parts are received an electric shock. | Type of economic operator to whom the measure(s) were ordered: importer classification of the control of the co | | | i | https://ex.eumosa.eu/hall stb:gatib. darty.cysen/eu/hallpope (2-dem/boses) 2009553 | | | | | |
| Serious risk | Professional | SR/02970/25 | Germany | Germany | No | Anjuries | The product does not comply with the logulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate technical units intended for such vehicles. | Bus | Lions City 12 E, Lions City 18 E | y Bus | Man | Motor vehicles | e1*2018/RSS**00065** *14(8.2018.8SS.003), *1*2018/RSS**00066** *14(8.2018.8SS.004) | | tive The foner retaining clips might be missing in some modules of the vehicle's roof battery cover. The missing brackets may cause the battery cover to crack along some of the connecting component and cause part of the roof battery cover to shear off, which could cause an accident and injuries to road users. | 5 | Type of economic operator taking notified measure(s): Manufacturer Category of measure(s): Recall of the product Date of entry into force: Linknown | Sweden | | https://ec.europa.eu/uaf ebr-patte: alersi/screen/wohlle.por //alersbetai/10095514 | | 600 | 22 SSTR | 1.08.2024 - 13.06.2025 | |
| Serious risk | Consumer | SR/02947/25 | Gechia | People's Republic of China | Unknown | Chemical | The product does not comply with the REACH Regulation. | | | Set of twelve toy rings with different coloured stones. | Ted dies | Toys | | 8600000 - Toys / Games | The product has an excessive concentration of lead (massured value 4.99% by weight), tead is harmful to human health, accumulates in the body, can cause developmental neurotaxisticy and may affect breast-fed or unborn children. | 1 22 | Type of economic operator taking notified measure(s): Importer Category of measure(s): Withdrawal of the product from the market bate of entry into force: Unknown | | | https://ec.europa.eu/ud 85 es-pate- alerts/screen/woble-por //alertDatail/10095512 | 92190311322 | | | Pini sha | k plastic box in the pe of a heart. |
| Serious risk | Consumer | SR/03015/25 | France | People's Republic of China | No | Electric shock | The product does not comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1. | USB charger | Chargeur | USB charger with two sockets. All batches are concerned. | iHower | Electrical appliances an equipment | d H141 | 78000000 - Electrica Supplies | If the insulation of the product is inadequate. The user could receive an electric shock from accessible live parts. | | Type of economic operator taking notified measure(s): Retailer Category of measure(s): Recall of the product from end users Date of entry into force: 24/05/2024 | | https://rappel.comio.gou v.fr/fishe-rappel/2024- 05-0046 | https://ec.europa.au/sal 9tr_gate: alerts/screen/web/appr t/alertbetail/10095520 | 50299842131 | | | | |
| Other risk Sewols | Consumer | 09/00128/25 | Monaka | People's Republic of China | No | Sectric shock | The product does not comply with the comply with the requirements of the Love Voltage Directive nor with the European standard 6 N 62368-1. | Adaptor | | White adaptor with one USB construct and one USB construct and one USB construct. | HADUE | Oscirical appliances an equipment | (C-114 | 7800000 - Electrica Supplies | The product's insidency is larger product, several in language profuse, leaving the parts accessible. The user could beauth as user could beauth the accessible and the accessible and accessive an electric shock. | | Type of economic operator taking notified measure(s): Distributor Category of measure(s): Distributor Category of measure(s): Warming consumers of Data of entry into force: Unknown operator taking notified measure(s): Distributor Category of measure(s): Distributor Category of measure(s): Distributor operator taking notified operator taking notified operator taking notified category of measure(s): Recall of the product from and users: Data of entry into force: Unknown | | | Manufacture accepts and an accept to the parties of | H4356/900055 | | | plane | otheard box with a stic window. |
| Other risk breads | Consumer | 04/90223/25 | Slovatia | People's Republic of China | No | flectric shock | The product does not comply with the requirements of the Low Policiage Directive nor with the European standard ft N 02368-1. | Adaptor | UNIVERSAL CHANGER | Black adaptor. | Piome* | Oscerrical appliances an equipment | g (T-1250 | 78000000 - Electrica Supplies | If the product's insulation, leaving to inappropriate, leaving the parts accessible. The control of the product accessible to the product accessible | i | Type of economic operator taking notified measure(i): Distributor Category of measure(i): Distributor Category of measure(i): Distributor Category of measure to the product from and tuars to the product from and tuars to the control of the category of measure(i): Distributor of measure(i): | | | Inter Life agrees avoid Methods for the state of the stat | 33772281776 | | | Car plan | otheard label with stic blister. |



| Serious risk | Consumer | 54/029-89/25 | France | People's Republic of Olina | No | Chemical | The product does not comply with the comply with the comply with the comply and the complex of t | F Soft toy | uszy ball | Soft toy in the shape of a furry bulk, in various the product area to product area concerned. | | Тоус | | 8600000 - Toys / Games | The migration of chromism V from the tops too high (measured value 0.34 measured value 0.40 measured value | CC We pp DO UM The GO GO GO GO GO GO GO GO GO GO GO GO GO | ripe of economic were too taking notified behalf and the property of the third the too the third the too the third the too the third | 12 12 12 12 12 12 12 12 | nps://rappel.comp.gov fr.ffichus.spops/2005. 20192 | onten Free aurone australia eta alduri eta a | 95066990 | | | |
|-------------------|----------|--------------|----------|--------------------------------|-------------|----------------------|--|-------------------|-----------------------|---|---------------|--|-----------|---|--|--|---|---------------------------------------|---|--|---------------|---|----------------------|----------------------------|
| Serious risk | Consumer | \$4/02984/25 | Stovakia | Puople's Regulatic of China | No | Bectric shock | The product does not comprehensive the comprehensive compr | Travel adaptor C | | White universal travel adaptor. | Katart | Electrical appliances and equipment | CDQ-074 | 78000000 - Electrical Supplies | The product's earthing protection is a subsection in a subsect | Curve of the curve | coloute controlled and controlled and coloute | | | https://ec.eurona.eu/led etr.gettu (genturianen/eurotegor (genturianen/eurotegor (genturianen/eurotegor | 5907481110042 | | | aard label and blokker. |
| Serious risk | Consumer | \$R/02959/25 | Sweden | People's Republic of China | No | Environment | The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS Directive). | Glove G | LOVELAMP | Glove for the right hand with LED lights. | | Clothing, textiles and fashion items | | 67000000 - Clothing | The solders in the product have an excessive concentration of lead (measured value: 69.5 % by weight). Lead poses a risk to the environment. | op m Ca W pr Du 18 | ype of economic period taking notified reasure(s): Importer ategory of measure(s): fithdrawal of the roduct from the market ate of entry into force: 8/06/2025 | | | https://ec.europa.au/saf etv.eute. alerts/creen/webRepor t/alertDetail/10095537 | 2457054247444 | | Cardboa | aird bax. |
| Serious risk | Consumer | \$R/02971/25 | Sweden | People's Republic of China | No | Environment | The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive). | | 30" Head lamp ULTRA | | | Hobby/sports equipment | | 82000000 - Tools / Equipment - power | The solders in the product have an excessive concentration of lead (measured value up to 69,3% by weight). Lead poses a risk to the environment. | os m Ca | upe of economic perator taking notified sessure(s): importer ategory of measure(s): (thdrawal of the roduct from the market ate of entry into force: 8/06/2025 | | | https://ec.europa.eu/saf etr-pate- alerts/creen/webflepor t/alertDetail/10095538 | 4743302761328 | | | sard box |
| Serious risk | Consumer | SR/02972/25 | Sweden | People's Republic of China | No | Environment | The product does not comply with the requirements of the Directive on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 Directive). | LED headlamp U | IST Tight Light 1.0 | Orange headlamp. | | Electrical appliances and equipment | G1T0109 | 7800000 - Electrical Supplies | The solders in the product have an excessive concentration of lead (measured value: up to 2.6% by weight). Lead poses a risk to the environment. | op m Ca W pr Du 29 | ype of economic perator taking notified esesure(s): Importer ategory of measure(s): fithdrawal of the roduct from the market ate of entry into force: 8/05/2025 | | | https://ec.europa.au/saf etx-patk- alents/screen/webflepor t/alentDetail/10095543 | 811747024316 | | Orange a package. | and grey blister e. |
| Serious risk | Consumer | SR/02954/25 | Germany | Vietnam | Unknown | Entrapment | The product does not comply with the General Product Saliny Regulation. | Felding chair | | Wooden deck chair with a folding frame and fabric seat in various cotours and patterns. Product sold online, in particular via tkmaoc.com/de | Urban Bälkony | Furniture | 43302DECK | | Due to an inadequate locking mechanism, the chair can easily collapse. This may result in the user's fingers being trapped inside and crushed. | | perator taking notified acture[s]: importer takeport of measure[s]: ecal of the product om end users atte of entry into force: 8/07/2025 | land, Poland in | tos: (Pueve timiaes co Nisplike II fereduktrusch d | https://ice.europa.au/saf dre_data. saters/screan/webflapor (FalentDetail/10095545 | | 99160 99161, 99162, 99163, 99168, 99169, 99169, 99170, 99371, 99372, 99376, 99377, 99378, 99379, 99379, | | |
| Other risk levels | Lonsumer | 08//00177/25 | Prance | People's Republic of China | LIVIKIOOWIS | Choking | comply with the requirements of the Toy Salety Roccive nor with the European standard EN 71-1. | Soft toy S | | Excreme cent say in prink and base (Dissey character from the Lio & Sitch carnons) with simulated breathing. All butches are concerned. Product sold centine, in particular via magic parts. If | | Toys | | | The fibrous stuffing material of the toy is easily accessible due to the weakhouse of the seams account the battery. A small child may put the filling material in the mouth and choke. | Recommendation of the commendation of the comm | geo of economic permetro taking notified secure(4): Importer takepoyn of measure(4): Importer takepoyn of measure(4): Importer takepoyn of this product takepoyn of takepoyn of takepoyn of permetro takepoyn of takepoyn of takepoyn of takepoyn of takepoyn of takepoyn of takepoyn of takepoyn of takepoyn of measure(4): Importer takepoyn of measure(| b. | ttes/Iransel como gene Inference agent 2005. 5-0161 | Mino, If the autono author ship gate, white gate, when the consequence of the consequence | | | | packaging. |
| Serious risk | Consumer | SR/02921/25 | ttaby | People's Republic of China | Unknown | Electric shock, Fire | The product does not comply with the requirements of the Low Voltage Directive nor with the European standards EN 60335-1 and EN 60335-2-30. | Electric heater A | lffreude - Air heater | Portable electric heater. Product sold online, in particular via Amazon (ASIN: 808GHGX6WX). | Amazon | Electrical appliances and equipment | XH - 1201 | 7200000 - Home appliances | The product is not resistant enough, leaving live parts accessible if subjected to mechanical stress. The user could stouch the accessible ires parts and receive an electric shock. Additionally, the plastic casing is not sufficiently resistant to heat and can catch fire. | Type of economic operator to whom the measure(s) were ordered: Importer Category of measure(s): Ban on the marketing of the product and any accompanying measures Date of entry into force: 21/01/2025 | Ger | many, Lusembourg | | https://ec.europa.au/saf viry.pate. skens/scieun/webliepor t/akent/betail/16095551 | 9559976086668 | | Cardboid | rd box. |



| Serious risk | Consumer | \$R/02977/25 | France | France | No | leguries | The product does not comply with the Regulation on the approval and market surveillance of motor whicles and their trailers, and of systems, components and separate technical units intended for such whicles. | Passenger car | C4 II | Passenger car. | CITROEN | Motor vehicles | 62*2007/46*0040*00 62*2007/46*0040*01 62*2007/46*0040*02 62*2007/46*0040*03 62*2007/46*0040*04 62*2007/46*0040*04 62*2007/46*0040*07 62*2007/46*0040*11 62*2007/46*0040*14 62*2007/46*0040*14 | 7700000 - Automotive | The airbag may deteriorate over time and if deployed, excessive internal pressure may cause the inflator body to burst and metal fragments could pass through the cushion material causing injury to occupants. | Fyga of aconomic operator taking in measure(s): Manufacturer Category of measure(s): Manufacturer Category of measure(s) and the measure Request to stop do Date of entry into 28/07/2025 | Cyprus, Croatia, Hungary, Lusembourg, Slovenia resistivity iving force: | https://ec.europa.au/sal etw.phte- alerts/screen/webReper UalertDetail/10095552 | | N | 5M3 19/11/20 13/02/20 | 09 - | |
|---------------------------|--------------|----------------------------|---------|-------------------------------|---------------|-----------------|--|---------------|----------------------------------|---|-----------------|--------------------------------------|--|--|--|--|--|---|---------------|-------------------------------------|--|--------------------------------------|--------------------------------------|
| Serious risk | Consumer | \$8/\02957/25 | Hungary | United Arab Emirates | Unitedown | Chemical | The product does not comply with the country Products Regulation. | Perfumi | | Eau de parfum, 100 ml. | Zoya Collection | Cosmetics | Woody & Lavender | | proport active products and account of the products. BMHCA may have the reproducts the products and the products are products and the products and the products and the products are products and the products and the products and the products are products and the products and the products are products and the products and the products are products and the products are products and the products are products and the products are pr | Type of Securious Construction of the Management of the William Management of the William Management of the William Management Operations of the William Construction of t | | Inter The auroba muhal strength: International meditage (International meditage) (International Tomas (International International International Internation | 5423080600351 | | | | tis in a blue diseard box. |
| Serious risk | Consumer | SA/(C2976/25 | France | france | No | injuries | The product does not comply with the Regulation on the Agepulation on the Agepulation on the Agepulation of the Agepulation of March 1997, which is and their shalker, and of systems, and of systems, and of systems and under the Agepulation of March 1997, which is a supplementation of the Agepulation of March 1997, which is a supplementation of the Agepulation of March 1997, and the Agepulation of M | | D54, D55 | Passenger car. | CITROEN | | 627 2007 J467 G0407 G 247 247 247 247 247 247 247 247 247 247 | 77000000 - Automotive | The airsig may deteriorate over time and if deptoyed, executive and if deptoyed, executive may cause the pressure may cause the inflator body to burst and metal fragment to could pass through the cushion material causin | Imitation (4): Manufacturer and Control of the Cont | | other Une average auchal services and the services auchal services and webbagger flakes the services and services auchal services and services auchal services | | | 3043 309(02)26 99(02)26 95(95)26 93(95)26 | 111.1 181.055 110 - 117.054 | |
| Sentous risk | Consumer | \$A/0293A/25 | taly | Spain | No. | Injuries | The product does not comply with the Regulation on the Regulation on the Application of the Regulation of Moreover and the Regulation of motor whichica and their straker, and of systems capacitate technical units intended for such whichica. | torry | SWAY, X-WAY, T-WAN | , Lony. | heco | | #27907/46 #27207/46*0179*19-12-24 #27207/46*016*23, #27207/46*016*23, #27207/46*018*27*22, #23, *25, *26, #27207/46*018*21*22, #23, *25, *26, #27207/46*018*21*22, #27207/46*018*21*22, #27207/46*018*21*22, #27207/46*018*21*23, #27207/46*018*23, #27207/46*018* | | The whole's steering guidron frastion or guidron frastion or for any store due to an incorrect sightening torque. This may laid to uncontrolled driving condition, austing injuries. | Type of consorting control tables; en experience tables; en experience tables; en experience tables; en experience de la consorting de la consortina de la cons | ire(s): | Inter Che uneven au had ein gatte. Silvert Viceseum / webflager (Jaker That all / 10095-65) | | | ales Y | | |
| Serious risk | Professional | \$R/02987/25 | Croatia | Estonia | No | Microbiological | The product does not comply with the Bloodial Products Regulation. | Antikeptic | DISSO SCRUB | Antiseptic detergent for hand washing in the ward, preoparative surgical hand washing and preoparative antiseptis of the patient's skin | | Chemical products | CHEMI-PHARM | 4700000 - Cleaning / Hygiene products | bacteria. In healthcare settings, particularly involving immunocompromised or vulnerable patients this bacterium can act as a opportunistic pathogen and pose a potential risk, such as uninary trac or wound infections. | ± | | https://oc.auropa.au/raf str_site: alerts/screen/webflepor f/alertDatail/10095962 | 4742124608123 | 143031024 443170125 143310125 | | Plast | tic bottle |
| Serious risk | Consumer | SR/02994/25 | Czechia | Ukraine | Unknown | Chemical | The product does not comply with the Cosmitte Products Regulation. | Facial gel | Gentle facial wash | Facial gel. | Green Pharmacy | Cosmetics | | | According to the list of ingredients, the product contains 2-(4-sert- butylbenzyl) propionaldehyde (BMHCA), which is prohibited in cosmetic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | Fyee of economic operator taking in measure(s) Exercises of economic operator taking in measure(s) Exercise (s) Exercises or of measure product from the Date of entry bid (s) Exercises of economic (s) | outor ire(s): market | https://cc.ouropa.eu/salesy.edu- esy.edu- alerts/screon/wohlkepor f/alerthatail/10095573 | 5904567050124 | 23561 | | | wn plastic bottle n a white pump. |
| Serious risk Serious risk | Consumer | SR/02999/25 SR/02965/25 | Sweden | People's Republic of China | Unknown | Chemical | comply with the REACH Regulation. | Bracelet set | Boho wooden bracelet 4Pcs/Set | with charms. Product sold online, in particular via AliExpress. | Not specified | Clothing, textiles and fashion items | 757892754215 | 6400000 - Personal accessories 64000000 - Personal | The product has an excessive concentration of cadmium; femeasured value up to 40% by weight]. Cadmium is harmful to human healt because it accumulates in the body, can damage the kidneys and bones and it may cause cancer. The product has an | Figure of accomment, operator taking in measure(s). Distall, Category of missis Withstrawal of the bid of the category of missis Withstrawal of the bid of the category of missis Withstrawal of the bid of the category of missis Withstrawal of the bid of the category of missis Withstrawal of the bid of the category of the bid of t | sutor re(s): market force: | https://do.europa.au/sal sty-jate. alertificrean/webflagor f/alertificrean/sebflagor f/alertificrean/100095572 | Not specified | Not specified | | | board sheet. |
| pendus risk | Lonsamer | per vi2965/25 | powedů | People's Republic of China | LITTELESCOMES | unettisCal | The product does not comply with the REACH Regulation. | noring | INKEYO FING | Metal ring, Product sold online, in particular via All Express. | reor specified | Clothing, textiles and fashion items | pomuží | 6400000 - Personal accessories | The product has an excessive concentration of cadmium (reasured value up to 83.5% by weight). Cadmium is hareful to human healt because it accumulates in the body, can damage the kidneys and bones and it may cause cancer | Fype of economic operator state of perator state of processing of measure(s); Data Category of smass Withdrawal of the state of entry into 26/06/2029 | eiffied vutor rereigi: market force: | httes://sc.europa.au/sal ety-pata- atents/screen/weblapor t/atentberail/10095573 | vuc spēcifiéd | mor spécifiéd | | Plast | Is Dog. |



| Serious risk | Consumer | SR/02997/25 | Sweden | People's Republic of China | No | Chemical | The product does not comply with the REACH begulation | Plastic sandals | Women's Summer PVC Sandals | Transparent sandals made of PVC. Product sold online, in particular via AliExpress. | | Clothing, textiles and fashion items | 774445464520 | 63000000 - Footwear | The product contains dibutyl phthalate (DBP) (measured values up to | | Type of economic operator taking notified measure(s): Distributor Category of measure(s): | | | https://ec.europa.eu/saf ety-pate- sleets/screen/webitener | | | Plastic bag. |
|--------------|----------|--------------|---------|-------------------------------|----------|-------------|---|---|--|--|----------------------------------|---------------------------------------|--|---|--|---|---|--------------------------------|----------------------------|---|---------------|--------------|--|
| | | | | | | | | | | | | | | | (measured values up to 34.3% by weight). This pithalate may harm the health by causing possible damage to the reproductive system. | | Withdrawal of the product from the market Date of entry into force: 26/06/2025 | | | t/alertDetail/10095575 | | | |
| Serious risk | Consumer | SR/02980/25 | Sweden | People's Republic of China | No | Environment | The product does not comply with the requirements of the birective on the restriction of the use of certain hazardous substances in electrical and electronic equipment (RoHS 2 | Smart watch | Multifunction Smart Watch | Smart watch with USB cable. Product sold online, in particular via AliExpress. | | Clothing, textiles and fashion items | 766926285317 | 6400000 - Personal accessories | The solders in the product have an excessive concentration of lead and cadmium (measured values up to 78.6% and 0.2 % by weight respectively). Lead poses a risk to the | | Type of economic operator taking notified measure(s): Distributor Category of measure(s): Withdrawal of the product from the market Date of entry into force: 26/06/2025 | | | https://ec.europa.eu/saf etv-pate: alerts/screen/webRepor t/alertDetail/10095576 | | | White cardboard box. |
| Serious risk | Consumer | SR/02982/25 | Sweden | People's Republic of China | No | Environment | the product does not comply with the | Headphones | Over Ear Wireless | Wireless headphones with a USB cable. | Fashion Boutique | Electrical appliances and | P2961 | 78000000 - Electrical | tead poses a risk to the environment and Cadmium bio- accumulates and poses a risk to the environment. The solders in the product have an | a - | Type of economic | | | https://ec.europa.eu/saf | 9760560054202 | | Black and white cardboard box. |
| | | | | | | | veguirements of the Directive on the use of socialities of the use of socialities of the use of socialities of the use of socialities of | | Bluetooth Headphones | Product sold celline, in particular via AlfEpreso. | | equipment. | | Supplies | excessive concentration of lead (measured value up to 73 95, by weight). The plantic membral of the plantic membral | У | operator taking notified measure(s): Distributor measure(s): Distributor Category of measure(s): Whitdrawal of the Whitdrawal of the product from the market product from the market 26/06/2029 yinto forect. | | | estigation distribution (Periodic Periodic Perio | | | |
| Serious risk | Consumer | \$8/00981/25 | Sweden | Prople's Republic of China | Airknown | Environment | The product does not comply with the requirements of the requirements of the processor on the vestriction of the use of versals hazardous and electronic equipment (Barts 2 Directive). | tarasks set | Workless Karackle Speaker Speaker Sources Connect. | Workelses Skrauhke speaker and miscophones set with a USS cable. Product sold online, in particular via Shelin. | Colorful karacke sound system | Gertrical appliances and equipment | 612 | 7800000 Bectrical Supplies | The others in the product have an excessive concentration of lead and cadmium threasured values up to 72 years and 72 year | a d | Type of economic | Germany France reland Scornia | | ompouffice current as had set patter. stitutifice con free billione con free billio | | | White cardinard bess. |
| | | | | | | | comply with the flegulation on the approval and market unveillance of motor vehicles and their trailers, and of systems, components and separate technical units mended for such whicks. | Passenger van / Light commercial vehicle | Transit Connect | Passenger van / Light commercial vehicle. | | | 4 SSU, 613**2012(858*00342*0 3 - **O4 (SKN), | | may freeze giving the take impression that the series before the white is clear, despite the white is clear, despite the presente of people or obstacles thems. This of scales has been a series of scales and series general failure and series general failure and series general failure and series of scales of sca | a d | operator taking notified measure(s). Manufacturer Category of measure(s): Manufacturer Category of measure(s): Racall of the product from and user: Date of entry into force: Unknown | | amport (recalls, details). | utre patie. date jate in the patient week the patient of the pati | | | |
| Serious risk | Consumer | \$6,0226,75 | Hungary | United Arab Emirates | Uniknown | Chemical | The product does not comply with the Committee Products the Committee Products Regulation. | Parfume | Supreme Musik | Eau de parfum, 100 ml. | Bait Al Bakhoor | Counetics | | S300000 - Beauty / Personal care / Hygiene | contain 2-(4-tert- burylbenzyl) propionaldehyde (BMHCA), which is prohibited in cometic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | ordered: Distributor Category of measure(s): Ban on the marketing of the product and any accompanying measure: Date of entry into force: 13/02/2005 | | | | hattas File aumaja au half ari gatta. Sherti Vicerean I wohlkejor Crafer Toota al 1 10005386. | 6296171070238 | 99A(730)/304 | Silver-schover glass, bottom in substant bottom in substant sorthware Sen. |



| Services risk | Consumer | 34/(02/25/25 | Hungary | or o | Chemical | The product does not accomply with the camply with the cample with diedes suguistion. | Porturna | Citiomana (fau de parl | | s Pergolése Paris C | Counertics | | | harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | Figure of excoloration and the control of the cont | | Hilling 2 Fair and State Control of the Control of | 3/00/35/00/35 | 156/16 | Cardboard Box. |
|---------------|-----------|--------------|---------|--|-------------------------|--|-----------------------------|--|--|---------------------|------------|---------|---|--|--|------------------------------------|--|---------------|------------|-------------------------------------|
| Sentous risk | Concurner | 58//02994/25 | mungary | Ontad Arab Emirates Or | Ommical | The product does not comply with the Cooping with the Cooping with the Cooping Coop | Perfume | Ease de partir for mee and entre for mee and entre for a great ent | women, 50 bottle. | endan C | Cosimetics | | | health of the unborn child and may cause skin sensitisation. | operator for whom the missource(i) were missource(i) were Category of missource(i). Withdhowaid of his missource(i) Withdhowaid of his missource(i) Albo(2) 2005 Missource(i) Mi | | http://ec.europa.au/co. | 6291107893603 | | Cardboard box. |
| Serious risk | Consumer | S#/02951/25 | Poland | Respir's Republic of Or | Siftication Siftication | The product does not comply with the requirements of the Top Safety Directive nor with the European standard Its 73-1. | Musical toy | Muscail mat interactive and for mark for children and for child dimensions. | musical toy free, 110 x 36 cm. | Ī | Тоу | UN123-2 | B6000000 - Toys / Garnes | The plastic of the packaging is too thin. If a child plays with the packaging, the plastic can cover the mouth and more, causing the child to sufficiate. | Type of economic operator taking miles of the control of the contr | ad s3): d | Begging the company and and an extra selection of the company and a | 6220179529949 | | Cartifloand thos and plass tic bag. |
| Serious risk | Consumer | SR/02939/25 | Poland | Pacole's Republic of Ur China | injuries | The product does not comply with the requirements of the hold doctors of the Machinery Directive no with the Commission becision 2012/32/EU prohibiting the placing the producting of participations for portable hand held brush outers. | Attachment for brush cutter | Blade St Laid Blade cutting law cutting law comprises s sinvier that for cutting law product sol particular Albaba con (dentificate) | I online, in a in number: 324). | ool h | Machinery | | | The rivets attaching the knives to the flail- cutter's main body could break. The knives might break. The knives might consequently detach during use and hit the user, causing injuries. | Type of economic operator taking method in measure(s). Other Category of measure Removal of this produ- lating by the oritine marketsplace on the category of the category of the category of the category of the category of the category of the category of the category of the of the category of the category of the of the category of the category of the of the category of the category of the category of the of the category of the category of the category of the of the category of the category of the category of the of the category of the category of the category of the category of the of the category of the category of the category of the category of the of the category of the cate | oe: | interest of first annuages are un- tilled to the control of the control of the select of control of the control of the United Section (Control of the control of the United Section (Control of the control of the contr | | | |
| Serious risk | Consumer | SR/02948/25 | Potand | People's Republic of Ur China | lejurias | The product does not comply with the requirements of the Machinery Directive nor with the Commission Decision 2012/32/EU prohibiting the placing on the market of flial-type cutting attachments for portable hand-held brush cutters. | Attachment for brush outser | Chain trimmer head Fail-type c. Printermer head characterise of Product solo particular v. Alfababa con (deemficials 100132245) | tting with two ains. online, in a in number: 313). | , | Machinery | | | The bolts or rivets attaching the chains to the flail-cutter could break. The chains might consequently detach during use and hit the user causing injuries. | Type of economic operator taking nearly income measure(s). Other measure(s), other m | od si): cct | https://ec.europa.eu/na streatie. steety/screen/weblepo //aiertSrtaal/10095591 | | | |
| Serious risk | Consumer | SR/02944/25 | Poland | People's Republic of Ur China | thrown trjuries | The product does not comply with the requirements of the Machinery Directive nor with the Commission Decision 2012/32/EU prohibiting the placing on the market of flair-type cutting attachments for portable hand-held brush cutters. | Attachment for brush cutter | Universal Chain Trimmer Head 65Mn Head 65Mn Chiminar Product solitoria Product solitoria particular Allaba con (desmirasi 160142704 | with two ains. ionline, in a an number: 306). | 5. | Machinery | | 8100000 - Lawn / Garden supplies | The bolts or rivets attaching the chains to the flail-cutter could break. The chains might consequently detach during use and hit the user causing injuries. | Type of sconnents operator taking nordification properator taking nordification measure(s). Other Category of measure(s) femous of this profits femous of this profits marketplace Date of entry into fore 01/08/2005 | cor | https://ec.auropa.au/ia stbs.latit. lateri.fcream/newillacons t/alert.brt.al/10095502 | | | |
| Serious risk | Consumer | SR/02937/25 | Poland | People's Republic of Urr | lajuries | The product does not comply with the requirements of the Machinery Directive nor with the Commission Decision 2012/32/EU prohibiting the placing on the market of flail-type cutting attachments for portable hand-held brush cutters. | Attachment for brush cutter | Brush Cutter Chain Trimmer Head thatchment dhainsare of Product sol particular vi Alibaba con (identification) | tting Adeytos with two aims. conline, in a conline, in a conline aims. c | ns h | Machinery | | 81000000 - Lawm / Garden supplies | The bolts or rivets attaching the chains to the flail-cutter could break. The chains might consequently detach during use and hit the user causing injuries. | Type of economic operator taking nation (see and taking nation (see and taking nation (see and taking nation)). The control of this proof of measured flammous of this proof, is string by the contine marketplace Date of entry into fore 0x,169,200.5 | Germany ed csc sistematics csc sec | https://ec.europa.au/hu/ sty-plate- sters/crean/web/leopola sters/crean/sec/leopola sters/crean/sec/leopola | | | |
| Serious risk | Consumer | SR/02945/25 | Crechia | Germany Ur | Chemical | The product does not comply with the Cosmics Products Regulation. | Hair foam | AIR DRY VOLUME Hair styling | loam. syoss | C | Cosmetics | | S300000 - Beauty / Personal care / Hygiene | According to the list of ingredients, the product contains 2-(4-bert- burylbarruy) propionaldelhyde (BMHCA), which is prohibited in cosnetic products. BMHCA may haren the reproductive system, may haren the health of the unborn child and may cause skin sensitisation. | Type of accounts Account of the control of the con | | ette si // rice dest note au fra ette sizité; plan et // rice seum (mais tille por six et // rice seum (mais tille por six et // rice sizité | 9000101092929 | 9924X72404 | Black bottle. |



| Serious risk | Consumer | SR/02962/25 | Czechia | Germany | Unknown | Chemical | The product does not | Hair gel foam | 3 WETTER MEGA STARK | Hairstyling gel foam, 150 | Schwarzkopf | Cosmetics | 1 | 53000000 - Beauty / | According to the list of | Type of economic | | 1 | https | ://ec.europa.eu/saf 4015000 | 291934C29D | | Black metal bottle. |
|-------------------|-----------|---------------|----------|-------------------------------|---------|--------------|--|--------------------------------|--|---|-------------------------|------------------------------------|----------------|--|--|---|---|---------|--|--|-----------------------|--|-------------------------|
| | | | | | | | The product does not comply with the Cosmetic Products Regulation. | | 5 | ml. | | | | \$300000 - Beauty / Personal care / Hygiene | According to the list of eigenedients, the production contains 2-4-eart-tourly liberary! propional dehyde (BMMCA), which is prohibited in cometic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | misionry) were ordered: Distributor Category of measure(s): Withdrawal of the product from the market Date of entry into force: 31/07/2025 | | | deren Jahren 1/Jahren | ate. Vicreen/weblieger rtbetail/1009595 | | | |
| Serious risk | Consumer | SR/02961/2S | Czechia | Germany | Unknown | Chemical | The product does not comply with the committee Products Regulation. | Hair dye | INTENSIVE COLOR CREME | Hair dye in a red colour, containing a 50 ml tube of colouring cream, a 50 ml bottle of developer, 10 ml sachet of caring mask and a pair of glowes. | Schwarzkopf Palette | Cosmetics | K16 MĚDĚNÝ REZ | \$100000 - Beauty / Personal care / Hygien | bulytberuyi) propionaldehyde (BMHCA), which is prohibited in cosmetic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | | | | https dtv.g alert t/ales | ://ec.swops.au/uaf 1000900 uaba: y/creen/webthops r10xtasl/10095596 | 0003464304 0009860238 | | Cardbaird box. |
| Serious ruk | Consumer | \$8,922966/25 | Mangary | France | Unknown | Chemical | The product does not comply with the comply with the Committe Products Regulation. | Perfume | Ottomane | Gas die perfum,100 ml. | Parfums Pergolden Paris | Cosmetics | Ottomaine | S300000 - Besity / Personal care / Hyglen | a ingredients, the product contains 2-(4-text burylebraye) propionaldehyde (BMHCA), which is prohibited in cosmetic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | measure(s) were ordered: Distributor Category of measure(s): Withdrawal of the product from the market Date of cetter into force | | | Section Section 19 and | The series while 1700001 The series with the series of th | 9 (1997) | | Cardboard box. |
| Other risk lewels | Consumer | ON/00129/25 | Shoughts | Neophi's Republic of China | No | | The product does not comply with the comply with the requirements of the Low Voltage Directive nor with the European standard EN 62368-1. | Adaptor | FAST CHARGE | white adaptor with one USB connector and one USB -C output. | YOUNZ | Gestrical agglances and equipment | 27 | 78000000 - Blectrical Supplies | The predest's insulation is inappropriate, basing the parties, basing the parties accessible. The superior parties are parties and parties are parties and parties are parties and electric | | Type of economic operator taking notified measure(i): Distributor(Category of measure(i): Distributor(i): Distributor(ii): Distributor(iii): Distributor(iii): Distributor(iii): Distributor(iiii): Distributor(iiiii): Distributor(iiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiiii | | nene daga daren Sulari | The entres solve 1009074 1009074 Information 1009079 1000074 1000079 10000079 1000079 1000079 1000079 1000079 1000079 1000079 10000079 1000079 1000079 1000079 1000079 1000079 1000079 10000079 1000079 1000079 1000079 1000079 1000079 1000079 10000079 1000079 1000079 1000079 1000079 1000079 1000079 10000079 10000079 1000079 1000079 1000079 1000079 1000079 1000079 1000 | 88840 | | Cardboard hox. |
| Serious risk | Consumer | SR/02940/25 | Poland | People's Republic of China | Unknown | | The product does not comply with the requirements of the Machinery Directive nor with the Commission Decision 2012/3/EU prohibiting the placing on the market of fial- type cutting attachments for portable hand-held brush outlers. | Attachment for brush cutter | | Flail-type cutting attachment with two chainsaw chains. Product sold online, in particular via Alibaba com (identification number: 1601486514648). | | Machinery | | 8100000 - Lawn / Garden supplies | The bolts or rivets stratching the chains to the filal-cutter could break. The chains might consequently detach during use and hit the user causing injuries. | | Type of economic operator taking notified measure(s): Other Category of measure(s): Removal of this product sking by the oriline marketplace Date of entry into force: 01/08/2025 | Germany | httos ety-p alerts 17ales | /fice.europa.eu/fid pte- siscenes/webflepor rtDetail/10095500 | | | |
| Serious risk | Consumer | SR/02956/2S | Poland | People's Republic of China | Unknown | injurius | The product does not comply with the requirements of the Machinery Directive no with the Commission Decision 2012/32/EU prohibiting the placing on the market of fiel- type cutting attachments for portable hand-held brush cutters. | Attachment for brush cutter | New Chain Type Grass Head for Various Thread Gasket Mower Parts & Accessories | Flail-type cutting attachment with two chainsaw chains. Product sold online, in particular with a Alibaba.com (identification number: 1601503585820). | | Machinery | 43 | 81000000 - Lieven / Garden supplies | The bolts or rivets attaching the chains to the filal-cutter could break. The chains might consequently detach during use and hit the user causing injuries. | | Type of economic operator taking notified measure(s): Other Category of measure(s): Removal of this product facting by the ordine marketplace Date of entry into force: 01/08/2025 | | hates dev. E alect 1/ales | office europa aufod ate. Viceren/webtleppr rtDetal/10095601 | | | |
| Services risk | Concurner | N/03004/25 | Stoogkia | Neoph's Republic of China | No. | Bectre shock | The product does no comply with the couply with the requirements of the Low Voltage Directive nor with the furgisear standard EN 62366-1. | Travel adaptor | Universal travel adapter | Universal travel adaptive in blad ediging visible to USB connectors. The use adaptive can be used in warrous types of sociaets. | LEGAMI | Gestrical agglances and equipment. | TARROOS | 78000000 - Electrical Supplies | Due to inadequate dissign, a plage of a class appliance requiring dissign, a plage of a class appliance requiring into the inserted into the protective acerthing can be into the secretarion for the provided for the connection of the provided for the connection of the provided for the connection of the protective conductor. Additionally, the adaptor allows two plage to the protection of the confidence of t | s | Type of economic operator taking notified measure(4): Distributor of the control | | Composition of the Composition o | The entire and the MRS9374 MRS | 1818462 | | Transparent plants bug. |



| Serious risk | Consumer | \$R/02950/25 | Poland | People's Republic of China | Unknown | Injuries | The product does not comply with the requirements of the Machinery Directive nor with the Commission Dacision 2012/32/EU prohibiting the placing on the market of fialitype cutting attachments for portable hand-held brush outlers. | Attachment for brush cutter | Trimmer Head | Flail-type cutting attachment with two chainsaw chains. Product sold enline, in particular via Alibaba.com (identification number: 1601517395521]. | | Machinery | Chairdaw Trimmer Head | 81000000 - Lawn / Garden supplies | The bolts or rivets attaching the chains to the flail-cutter could break. The chains might consequently detach during use and hit the user causing injuries. | | Type of economic operator taking notified measure(s): Other Category of measure(s): Removal of this product lating by the online marketplace Date of entry into force: 01/08/2025 | | | https://ec.europa.au/sal eth-pate- alent/screen/webliepor t/alentDetail/10095603 | | | | |
|--------------|----------|--------------|----------|-------------------------------|-----------|-----------------|--|---|--|---|-----------------|------------------------------------|---|---|--|---|--|---|--|---|---------------|--|----------|--|
| Serious risk | Consumer | SR/02996/25 | France | Republic of Korea | No | Microbiological | The product does not comply with the comply with the complete with the complete of the comp | Face cream | Centella Crème | Face cream, 50 ml and 20 ml tube. | Erborian | Cosmetics | 6AA20067, 6AA20068 | S100000 - Beauty / Personal care / Hygiene | The product may be microbiologically concurrenced with Candida paragolosis (and the paragolosis infections in some consumants and paragolosis infections in some consumers, particularly those with a weakened the same particularly those with a weakened and additionally lead to skin irradion and inflammation. | | Type of economic operator taking notified measure(s): Manufacturer Category of measure(s): Withdrawal of the product from the market Date of entry into force: Usahowan of the product from the market Date of entry into force: Usahowan Type of economic operator taking notified measure(s): Manufacturer Category of measure(s): Measuref of the product from and users: Date of entry into force: 25/07/2015 | | intp://inspell.comce.go. vs.Drichar.appell.2025. 07.6163 | entps://ec.auropa.eu/ud the enth- state the control of the control of the particles of the control of the control of the 17 June 10 vs. all 710055004 | | MAGESIAS MAGESIAS MAGESIAS MAGESIAS MAGESIAS | | Gerbloor box. |
| Serious risk | Consumer | 54/(0303)/25 | Stovakia | (Intercent | No | Electric shock | The product does not comply with the hospital product of the comply with the hospital product of the comply of the hospital product of the complete pr | Travel adaptor | Universal travel adapter | Universal white travel adaptor. | | Checrical appliances and equipment | 933. | 79000000 - Electrical Supplies | The product's earthing protection is inadequate, it allows for the simultaneous extraction of two plugs and it allows simple on the simultaneous phige insertion, leaving the plug insertion, several public phige insertion, several public phige insertion, several public phige insertion, several public phige insertion, several phige insertion, sev | | Type of economic operator taking notified caperator taking notified category of measure(s). Withdrawal of the product from the market Date of entry into force: Unknizowa Type of economic operator taking notified measure(s). Butchildren Category of measure(s). Recall of the product from end users. Date of entry into force: Unknizowa Type of economic operator taking notified measure(s). Place of the product from end users. Date of entry into force: Unknizowa Type of economic operator taking notified measure(s). Warning consumers of the take the product of the control of the risk. | | | Stiliga (Ten europea eur l'art Marigatte Marie Carriero (Leuke Marie (L'alert Carriero (Leuke Marie (L'alert Carriero (L'alert Carriero)) | 8817149484554 | PAT200930394087.4 | | Carlboard box |
| Serious risk | Consumer | SR/02975/25 | Poland | Sri Lanka | Unknown | Abrasion | The product does not comply with the Personal Protective Equipment Regulation (IPPE) nor with the European standard EN 388. | Protective gloves | MaxiFlax | Protective gloves. | atg | Protective equipment | 34-274, Elite, Elite 34- 274 9(L) | 8500000 - Safety / Protection - DIY | | Withdrawal of the product from the market Date of entry into force: 17/07/2025 | | Germany | | https://ec.europa.eu/sid ety-gate- alerts/screen/webRepor t/alertDetail/10095507 | 4792249054628 | | | Carboard attached to the product. |
| Serious risk | Consumer | SA/02964/2S | Hungary | United Arab Emirates | Unkingwan | Chemical | The product does not comply with the Counsels Products Regulation. | Perfume | Vanille & Patchouli | Eau de parfum, 100mi. | Zoya Callection | Cosmetics | | | | Type of economic operator to whom the measure(s) were ordered. Distributor Category of measure(s) were category of measure(s) and the product and any other companying measures Date of entry into force: 1,1002/2025. Type of economic operator to whom the measure(s) were continued on the continued of the product from the market with the product from the market by the product from the market but of entry into force: 1,1002/2025. | | | | other Une arrese surhal engine: shorts/screen/webbeger trakers/screen/webbeger trakers/screen/webbeger | 6423554524213 | | | Custioner bios. |
| Serious risk | Consumer | 54/02991/25 | Portugal | France | No | legiuries. | The product does not comply with the legislation on the legislation on the approval and market convenience of motor trailers, and of product trailers, and of product trailers, and of product components and legislation technical units intended for such with class. | Passenger van / Light Commercial vehicle | ISS, LIASSO, CAN, COPOIL, COSIO COSIO, GR Yaris, Highlander, RAVY, Yaris, Cross | Passenger car. | Lémus, Toyota | Motor whicks | 65*2007/46*0289*06, 65*2007/46*0289*07, 66*2007/46*0289*07, 66*2007/46*0289*07, 66*2007/46*0289*07, 66*2007/46*0289*08, 67*2007/46*0889*08, 67*2007/46*08, 67*2007/46*08, 67*2007/46*08, | | A flaw in the vehicle's combination moter or combination moter or combination moters or combination moters or combination of combination of control of combination of combi | | Type of recursivity operator basing notified measure(st): Imported the company of the company of the company of the product from end users. Date of entry into force: Unknown | Bulgaria, Cyprus, France, Hungary, Sweden, Scorenta | | Sente Africa currons muhad Erin galden Sente galden Sente galden Sente galden galden galden galden Sente galden galden galden galden (1984 et al.) 10099610 | | | 25SD-463 | 9027-905 |
| Serious risk | Consumer | SR/02963/25 | Cyprus | Unknown | No | Chemical | The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Toyslime | | Toy sime. | нарру Веаг | Toys | 22-03192 | - | The migration of boron from the toy slime is too high (measured value: 983 mg/kg). Ingestion or contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. | Type of economic operator to whom the measure(s) were ordered: Ratailer Category of measure(s): Withdrawal of the product from the market Date of entry into force: 26/05/2025 | | | | https://ec.europa.eu/sa/ 69-93te- 36ert/screen/web/Bases t/alert/betail/10095611 | 5230666957410 | | | Transparent plustic container in the shape a bear with a pink lid. |



| | | SR/02942/25 | | The state of the s | | | The product does not | | | | | Motor vahirles | e2*2007/46*0537*01 - | 77000000 - Automotive | Vehicles may have | | Type of economic Bulgaria, Cyprus, Fran | | | | 025.016 | 03.03.2016 - 08.07.2022 | |
|---------------|----------|--------------|----------|--|---------|-------------|---|--|--|--|--------|----------------|--|---|---|--|--|-----|--|------------------|---------|-------------------------|-------------------|
| Derindus risk | Consumer | | Portugal | Prance | No | tegunes | comply with the Regulation on the approval and market surveillance of motor vehicles and their trailers, and of systems, components and separate berhical units intended for such vehicles. | Passenger van / Light commercial vehicle | | a Passenger van / Light commercial vehicle. | Toyota | | 02*2007/46*053**01 - *18, 02*2007/46*0538**01 - *20 MO236#, MO234#, | | excessive corrosion on the front suspension arm bolt, due to the design in combination with environmental factors. As a result, the bolt may fall which may affect controllability of the vehicle and increase the risk of an accident. | | operator taking notified remassure(s); import, Sweden, slovenia Category of measure(s); import Category of measure(s); feecal of the product from end users Date of entry into force: Likiknown | .00 | https://ec.europa.au/sate she-gate: alerts/screen/webflepor t/alertDetail/10095612 | | | 93.07.2017 - 16.12.2021 | |
| Serious risk | Consumer | SAV029884/25 | Portugal | France | No | Environment | The product does not comply with the legitation on the legitation on the approval and market curvivillance of motor whicks and they trailer, and of systems, compound to compound the compound of systems, compound to see see see see see see see se | Pissionger van / Light commercial vehicle | Proace (Proace Verso), Proace City and Proace City Verso | | Toyota | Motor vehicles | MOZISIA, MOZ | | A calibration error in the Engine Electronic Control Unit (ECU) Software may prevent the Malfunction Indicator Lamp (ME) from activating when Indicator Lamp (ME) from activating when Software Cachipic Medicator Lamp (ME) from activating when software Cachipic Medicator Lamp (ME) Software Cachipic | | Type of economic Magents, Cyper, in Figure Special Company, Sweden, Company Francisco, Calegory of Brancisco, Calegory of Brancisco, Calegory of Brancisco | | https://ice.aurupa.au/ad/ stre.githe sites/s/crean/weblinger (ZalestCusta/)1009/6513 | | 025-027 | 07.017.16.12.2021 | |
| Serious risk | Consumer | SAV/02966/25 | Mungary | France | Unknown | Chemical | The product does not comply with the Country with the Country with the Country that the Country the Country that the Country the Country that | Perfume | Qud Saffron | Catz ait de perfum, 100 ml. | | Cosmetics | | | (BMH/CA, which is prohibited in cometic products. BMH/CA may harm the reproductive system, may harm the hash of the unborn child and may cause skin sensitisation. | orderies: Datritudos Category of messure(c): Withdrawal of the product from the market Date of entry into Broce: 13/02/2025 Type of economic operator to whom the messure(c): Western ordered: Datritudos Category of messure(c): Man on the marketing of the product and array accompanying messure(c): More of entry into Broce of entry into Broce: 13/02/2025 | | | https://ec.europa.an/url broughts- shers.h.crean/webleuce (Jahrs Duta/1909/635 | 6-200366-411.200 | | | Cardboard box. |
| Serious risk | Consumer | SAV02995,/25 | Mungary | France | Unknown | Chemical | The product does not comply with the Counselic Products Regulation. | Perfume | Xania | Getz alt die paerfum, 75 mi | Naorei | Cosmetics | | | prohibited in cosmetic products. BMHC may harm the reproductive system, may harm the health of the unborn child and may cause skin sensitisation. | operator to whom the measure(s) were ordered: Distributor Category of measure(s) the product and any accompanying measures take of early into force: 13/02/2025 Type of economic operator to whom the measure(s) were Category of measure(s) withdrawal of the product from the market bear of the product from the market 13/02/2025 Type of economic operator to whom the measure(s) were Category of measure(s): withdrawal of the product from the market base of early into force: 13/02/2025 | | | Hitter (Fee companion) of the paths site full common weathers 2 hier full common site 2 hier fundament (Fee common 2 hier | 3296523554237 | | | Cardboard box. |
| Serious risk | Consumer | SR/00005/25 | Hungary | United Arab Emirates | Unknown | Chemical | The product does not comply with the Counsels Products Regulation. | Perfume | | Gau de parfum, 100 mt. | AFRAN | Cosmetics | | S000000 - Beauty / Personal care / Hygiene | contains 2,44-set- buty/bensyl) propional/dehyde (BMHrCA), which is prohibited in cosmetic products. BMHrCA may harm the reproductive system, may harm system, may harm child and may cause skin sensitisation. | onderies: Darknoted Category of massure(s): Withdrawal of the product from the market Date of entry into Series: 13/02/2025 Type of economic operator to whem the messaure(s) were orderes: Distributor Category of messure(s): Ban on the marketing of the product and any accompanying measures take of entry into force: 13/02/2025 | | | ottes / Fre ceresa es subal fre jutte: sters fuere and event general subal fre fuere and a subal fuere and a laboration and a subal fuere | 6290171070375 | | | Purple paper box. |
| Serious risk | Consumer | SR/02941/25 | Portugal | traby | No | espuries | The product does not comply with the kagulation on the approval and market surveillance of motor vehicles and thair trailers, and of systems, components and separate technical units intended for such wehicles. | Passenger van / Light commercial vehicle | Proace Max and Proace Max BEV | Passenger van / Light commercial vehicle. | Toyota | Motor vehicles | e3*2018/858*00106*01, e3*2018/858*00106*02 | 77000000 - Automotive | When the driver deactivates and reactivates the Automatic Emergency Brake (AEB) in the same driving cycle, it will remain deactivated without a warning light indicating the deactivation. This may increase the risk of an accident. | | Type of economic logorator taking notified inungary, Sweden, Slovenia Category of massure(s): Category of massure(s) | | hetps://fec.europa.eu/saf elv-gate. slent/sceen/webflapor s/alestOutal/10096612 | | O25-026 | 94.10.2024 - 11.03.2025 | |



| Contains at 1 | Process . | Pro marror | - Harrison | Brookly B. C. C. | Listano - | Phonormal | The product does not | Key ring with doll | Description. | Key ring with a 20 cm | T | Tr | loor me | laranaer - | The plastic material of | Type of economic | | | | harrier . | 20740244007 | | | |
|--|------------------|--------------------|-------------|--------------------------------|------------|-----------|--|--------------------|--|--|----------------|---------------------------|--|----------------------------|---|--|---|-------------------|------------------------|--|--|--|--------------------------|---------------------|
| The second secon | and registration | etty van dudig aud | , managem y | Dhra | | | comply with the REACH Regulation. | | and production of the control of the | tall toy doll in tulle direct. | | | The state of the s | Garnes | the doll has an excision of bici2- cetylmen probability of the probabi | operator to whom the measure(s) were ordered. Distributor or clasgery of measure(s). Withdrawal of the product from the market Date of entry into force: 13/06/2/025 Type of economic operator to whom the measure(s) were ordered. Distributor of the product from the measure(s) were ordered. Distributor (actigony of measure(s): Recall of the product from end users. Date of entry into force: 13/06/2/2035 | | | | the path of the control of the contr | | | | |
| Servicus risk | Consumer | \$4/03922/75 | Hungary | Propile's Republic of China | Unikrosen | | The product does not comply with the REACH Regulation. | Plastic doll | jadék baba | Plastic toy doll. | Dress Girls | Toys | C.08305 | SECOCODO - Toys / Games | to their reproductive system. | measure(s) were confered to the product and any exception of the product and any exception of the product and any exception of the confered to | | | | Internal File Acceptance with a file of the patter. Start Victoria of weakingsor. Edward Victoria of Weakingsor. Edward Victoria of Vic | 88 150 00 83 150 | | Plantic blook | |
| | | | Mungary | Chira | Unknown | Chemical | The product does not comply with the REACH Regulation. | | New Baby | Plastic toy dolf, dressed in different coloured clothes. | | Yoys | | Games | | from end users Date of entry into force: 27/06/2025 | | | | https://e.worpea.en/us/ Shirp atte. Shirt Unit and Insalitation Shirt Unit and Insalitation Chairman (Insalitation Chairman) | 881600082329 | | Faunt coll cardboard | with sheet closure. |
| Serious risk | Consumer | SR/02978/2S | Poland | Poland | Unknown | Injuries | This product does not comply with the General Product Safety Regulation. | Bicycle wheels | | Bicycle whaels, Batches affected are manufactured and delivered from 1 August 2024 onwards and with DT Swiss ID number of 2740000 or higher. | SWISS SIDE | Hobby/sports equipment | HADRON* All-Road Ultimate 450, HADRO All-Road 450, HADRO Classic 500, HADRO Ultimate 500, HADRO Classic 650, HADRON Classic 650 | 2N2* P | A spontameous delamination, separating the carbon layers, of the rim flange may occur, significantly compromising the wheel's structural integrity. Due to this damage, there is an increased risk of accidents. | | Type of economic operator taking notified measure(s): Manufacturer Category of measure(s): Measure(s): Measure(s): Measure(s): Measure(s): Type of measure(s): Type of | Bolgaria, Ireland | https://www.dtswiss.co | https://ec.europa.eu/saf sth-pate. siersi/screen/webfleper (/alentDutall/10095625 | | | | |
| Servicus risk | Consumer | SA/02998(/25 | Mungary | Propile's Republic of China | Untrinowen | Chemical | The product does not comply with the REACH Regulation. | Plastic doll set | | Plastic God with bronds which The doll weeks a steer-elecs print dress. The Accessorie mice of the Accessorie middle Gpairs of high heals, 20 just of Bulletina Supris of Bulletina Supris of Bulletina Supris of Bulletina Supris of Bulletina, 1 hair dryer, 1 conto), 1 perfutne, 1 hapris, 1 micror, 6 feb 4p pan. | socie Pictures | Toys | NO.200 | scoccoto - Toys / Games | | product from the market Date of entry into force: 24/05/2025 Type of economic operator to whom the measure(s) were ordered: Distributor Category of measure(s). Ban on the marketing of the product and any accompanying measures Date of entry into force: 24/05/2025 | | | | attos 1712 arrama en har for patre ser patre starts for com / methops: Lawrithness (10046), 22 | 970442490155 | | Plantic bag cardinand | with |
| Serious risk | Consumer | SA/03010/25 | Plungary | People's Republic of China | Uniknows | Oroking | The product does not manyly with the comply with the constrainments of the Tay sharing breath or sharing breath or sharin | Soft toy | plush goose | White dot to yo in the dayse of a goose in the dayse of a goose and lags, and a sipper on the belief. | Torch | Toys | C22719 | BEOCOCIO - Toys / Games | Sentiliparts can easily elated high experience of the toy). As a consequence of the toy). As a consequence of the toy, as consequence of the toy, as a consequenc | Type of accessmin. operator to when the measure(s) were ordered. Distributor Category of measure(s): With drawal of the product from the enable product from the enable of the product from the market measure(s): Way of the constitution of the product of when the product from the force operator to when the measure(s) were ordered. Distributor category of measure(s): Category of measure(s): Category of measure(s): Category of measure(s): Data of entry into force: 05/05/2025 | | Stovakia | | atto UE e amena authal Ste patte destribuses en freshinger chalestifuse and metilinger chalestifuse at 17,009/628 | 881800227195 | | | |



| Springs risk | Consumer | 58/03014/25 | Hungary | Pannie's Renublic of | Unknown | Choking | The product does not | Soft toy | nlish ennse | White small soft to in | Tourh | Tous | C21281 | 86000000 - Tow / | Small narts can port | Tune of economic | | Slovakia | п. | etns flor ournes outset koos | 810212818 | | | | |
|---------------|----------|---------------|-----------|-------------------------------|--------------|-----------------|--|---|--|--|------------------|-------------------|--|---|--|---|--|------------|--|--|----------------------------|-----------------|--|--|---|
| parrosa rilik | _omsumé! | par(xxx)14/25 | pungery | учория и пёрыйс об Стіга | part 47,0000 | A-MATTINE | The product does not comply with the face comply with the face possibly Described now with the Gropean standard EN 72-1. | non Sty | pendid ground | White small soft toy in the shape of a goose with comps beak and legs. | rudell | гор | | 8500000 - Toys / Games | them in the mouth and choke. | Type of economic operator to whom the measure(1) was to whom the measure(1) was to will be considered. District the considered of the considered of the product from the market base of entry into force: 2006/2025 Type of economic operator to whom the measure(1) was obtained of the considered of the | | more BEE | 2 2 5 | Step / fee wwopa au/laf Sast Magata. Lanti-free au/n 100965-22 | secret del Did | | | | |
| Serious risk | Consumer | SR/03006/25 | Hungary | People's Republic of China | Unknown | | The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-1. | Easter egg toy set | | The product is composed of a set of 12 colourful silicone toy figures with colourful plastic egg-shaped capsules or of an Easter eggshell toy set with 10 colourful foam toy figures with colourful plastic egg-shaped capsules. | YWU. | Toys | | 86000000 - Toys / Garnes | | ordered: Importer Category of measure(s): Import rejected at border Date of entry into force: 27/05/2025 | | | <u>0</u> | ittos://ec.europa.au/saf fr-pate. iert/screen/webliepor calertDetail/10095530 | | | | | stic bag. |
| Serious risk | Consumer | 34/00/986/25 | Germany | Om Red Kingdom | No | Microbiological | The product does not comply with the comply with the Commits Products Regulation. | Skin chamesing wipus | Clarenda Reinigungstücher 5 in 1 | copoules. Sinc cleansing wipes for normal side and side a | CAMA | Cosmetics | | | The product is memberologically seed to be a seed of the control of the mescaphic archie bacteria Pluralbacter produced pattern may memberological may memberological contaments, particularly those with a weakened immune system. | | Type of exconesis: operator taking notified measure(s): Distributor Category of measure(s): Distributor for measure(s): Distributo | | enas Christianshmens (e. 1906) ommen de fiye sons fiye en en omdiforat fiye activit. The constitution of the constitution of the con- traction of the constitution of the con- traction of the constitution of the con- | International Conference of the Conference of th | 835446999 159927 519927 | 223 | | fia | w green rectangular to pack with a re- sable opening (closing p) |
| Serious risk | Consumer | SR/03000/25 | Lithuania | People's Republic of China | Unknown | Chemical | The product does not comply with the REACH Regulation. | Glue | Super Glue | Glue, two pieces of 3 ml | . Shenqiang | Chemical products | | 7000000 - Arts / Cra / Needlework | afts: The product contains chloroform (measured value 30.66 % by weight). Chloroform causes skin irritation, can be harmful to healt if inhalted or swallowed and is suspected to cause cancer. | Type of economic operator to whom the measure(s) were ordered: Retailer Category of measure(s): th Withdrawal of the product from the marke Date of entry into force Unknown | | | 2. 2. | https://ec.europa.eu/saf 6976 dr-gate- lests/screen/webRepor /alertDetail/10095632 | 6034465310 | | | Bis ba pla | ster with a cardboard ck and a transparent stic front cover. |
| Serious risk | Consumer | \$8/02992/25 | Germany | Türkiye | No | Fire | The product does not comply with the Regulation on the approval and market surveillance of motor whiches and their trailers, and of systems, components and separate technical units intended for such wehicles. | Pässenger van / Light commercial vehicle | Transporter | Passenger von / Light commercial vehicle. | 100 | Motor vehicles | e5*2018/858*00262* (NVN) | 7700000 - Automoti | various connections in the electric motor compartment (e-box) could lead to the interruption of various electrical functions, e.g. falare of the esterior lighting or loss of propulsion. In the event of an increase in resistance, it may lead a fire. | t to | Type of economic operator taking notified measure(s): Manufacturer Category of measure(s): Recall of the product from end users Date of entry into force: Unknown | | 20 20 20 20 | ttps://ec.europa.eu/ud re-pate- fersificrean/webBeacc (alertDetail/10095634 | | 97A3 | 15.02 | 2 2025 - 21.02.2025 | |
| Serious risk | Consumer | \$R/02988/25 | Cyprus | Unknown | No | Onemical | The product does not comply with the requirements of the Toy Safety Directive nor with the European standard EN 71-3. | Toyslime | SUPER COLOR | Toy slime in three colours. | | Toys | | 8600000 - Teys / Garnes | The migration of boron from the toy slime is to high (measured value us to 838 mg/kg). Inspection contact with an excessive quantity of boron may harm the health of children by damaging the reproductive system. | product from the marke Date of entry into force: 19/05/2025 | | | in de | etps://ec.europa.eu/sal tz-gitte fests/screen/mehilepor (alertDutail/10095637 | 205095288 | | | Tri co | resparent plastic stainer. |
| Serious risk | Consumer | \$4/00979/25 | France | Germany | No. | Injuries | The product does not comply with the comply with the Regulation on the approval and market surveillance of motor whichis and their entire components and separate technical units intended for such vehicles. | Passenger car | Signium, Voctor, Astro, Caccada, Merine, Zafira, Mokka | Passinger car. | Opel | Motor vehicles | 487 7000/1.185* 700.01* 194. ***E17000/1.185* 700.01* 194. ***ASSES OR.** ***SES OR.** ************* ****************** | 77000000 - Automoti | to the hardge may distribute over time and displayed, excessive internal pressure may count internal pressure may count internal may be a service of and metal fragments could pass through the could pass through the cushon material pass through the cushon material pass through the could pass through the could pass through the pass of pass through the pass of pass of pa | | Type of economic operator taking notified measure(s): Manufacture (Category of measure(s): Category of measure(s): Gaylor of measure(s | Luxembourg | 2 2 2 | title of the exercises a shall be gather. Here I for each process of the shall be gather. Here I for each process of the shall be gather. John Shall be gather in the shall be gathe | | in and a second | Marini 10.10 Molik 15.08 Vector 15.10 Zafirar 16.08 Signu 19.01 Astra 21.03 | \$2000 - 15.502.2017 was 23.06.3018 kg.2005 - 25.09.2008 kg.2005 - 25.09.2008 kg.2005 - 25.09.2008 kg.2005 - 25.09.2008 kg.2005 - 28.005 - 28.005.2008 kg.2005 - 28.005 - 28.005.2008 kg.2005 - 28.005 - 28.005.2008 kg.2005 | |
| Serious risk | Consumer | SR/U9011/25 | Czechia | Germany | Unknown | Chemical | The product does not comply with the comply with the Cosmetic Products Regulation. | Hair styling foam | ultra schaumfestiger | Hair styling foam, 150 ml. | Schwarzkopl/Taft | Cosmetics | 4 - Ultra stark | S300000 - Beauty / Personal care / Hygie | | Type of economic to operator to whom the measure(s) were ordered: Distributor Category of measure(s): Withdrawal of the product from the marke Date of entry into force: 05/08/2025 | | | | ttor/fice-wrope-su/sat 4015 **reptate- **sertifice-sen/webBener **calet- **sertifice-sen/webBener **calet- **sertifice-tail/1009641 | 09082 | 448460 | | A | minium bottle. |



| Serious risk | Consumer | \$R/09008/25 | Czechia | Germany | Unknown | Onemical | The product does not comply with the Cosmetic Products Regulation. | Hair styling foam | volumen schaumfestig | of Hair styling foam, 150 ml. | Schwarzkopf/Taft | Cosmetics | 5 - mega stark | contains 2-(4-tert- butylberayl) propionaldehyde (BMHCA), which is prohibited in cosmetic | logarator to whom the measure(s) were soldered. Contributor of the contributor of the contributor of the contributor of the contributor of the contributor of the contributor Cont | https://ec.aud eth.eath. abstrt/screen/ t/alertDutail/ | | 2525 | 9904248254 | Aluminium bottle. |
|--------------|----------|--------------|---------|---------------|---------|----------|---|-------------------|----------------------|--|------------------|-----------|----------------|--|--|--|--|------|------------|---------------------------------|
| Serious risk | Consumer | \$R/09001/25 | Crechia | Germany | Unknown | Chemical | The product does not comply with the Cosmette Products Regulation. | Scap | Vaseline scap | Soap | Kappus | Cosmetics | 3-0533 | contains 2-(4-teet- buly/benry() projocaldshyde (BMHCA), which is prohibited in cosmetic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause ski sensitisation. | locacutor to when the immunosity) were consistent of the consistent of the Calegory of measurem() Calegory of measurem() Consistent of the product Date of entry winto force of collections of the of collections of the collections of collections of | ete eatat abert/creen/ (/alertDutal/) | 0095643 | | 2440 | Stue and white cardboard box |
| Serious risk | Consumer | \$R/09007/25 | Crechia | Spàin | Unknown | Chemical | The product does not comply with the comply with the Cosmetic Products Regulation. | Deodorant | COOL & DRY 48H FRESI | Deodorant, advertised as having anti-perspirant action, 50 ml. | | Cosmetics | | contains 2-(4-tert- butylbenzyl) propionaldehyde (BMHCA), which is prohibited in cosmetic | logarator to whom the measure(s) were codesed. Relatable Codesed. Relatable Codesed. Relatable Codesed. Relatable Codesed. Relatable Codesed. Codes | intps://ec.aud fitps://ec.aud identificeanint f/alentDutal/j | pa eu/suf 360734741 vebRupor 005544 | 1611 | 9344 | Plastic bottle. |
| Serious risk | Consumer | SR/09012/2S | Crechia | United States | Unknown | Chemical | The product does not comply with the Constitute Products Regulation. | | LIFE ENERGY | Eau de toilette, 100 mf. | | Cosmetics | | contains 2-(4-sert- bully/benzyl) propional/dishyde (BMHCA), which is prohibited in cosmetic products. BMHCA may harm the reproductive system, may harm the health of the unborn child and may cause ski sensitisation. | Lossatura to when the missacretic) were uniformal fluid profit and profit and the control of control of the product David every wind force dashesses | ding date: detrificeening (/alertDutall/) | | | 5540 | Cardboard box. |
| Serious risk | Consumer | \$R/09009/25 | Crechia | Czechia | Unknown | Chemical | The product does not comply with the Constitute Products Regulation. | Eau de toilette | Red Men | Eau de toilette, 100 mf. | Slazenger | Cosmetics | 16938 | contains 2-(4-tert- butylbenzyl) propionaldehyde (BMHCA), which is prohibited in cosmetic | logarator to whom the missaure(s) were societies. Bestate resident to the societies to the societies to the societies product Date of refry into force. Uniform | respective and services are services and services and services and services are services and ser | <u>pa su/sul</u> 871125216 rehiterer 0095651 | 0385 | 023001 | Cardboard box. |