

# CONSUMERS

English (en)

¥

European Commission (http://ec.europa.eu/index\_en.htm) Consumers (http://ec.europa.eu/consumers/index\_en.htm) Consumers safety (http://ec.europa.eu/consumers/consumers\_safety/index\_en.htm) Safety products (http://ec.europa.eu/consumers/consumers\_safety/safety\_products/index\_en.htm)

Back to report listings

Go to Rapid Alert System home

# Rapid Alert System weekly update

# Report 16 (Published on: 22/04/2016)

Notification A12/0427/16 published in report n°14 of 08/04/2016 has been updated at the request of the notifying authority in order to clarify that the product is counterfeit.

Information on product identification (brand, product name) in notification A12/0394/16, published in report n° 13, has been updated upon request of the notifying authorities.

	event=m pa.eu/consumers/consu	umers_safety/safety_p	elVsn&web_report_id=1851) XML version oroducts/rapex/alerts/main/? LVsn&web_report_id=1851) Alert number		
	event=m pa.eu/consumers/consu	umers_safety/safety_p	elVsn&web_report_id=1851) XML version 🔂 products/rapex/alerts/main/?		
	event=m	ain.weeklyReportExce	elVsn&web_report_id=1851) XML version 謆		
		_ , ,_,	elVsn&web_report_id=1851)		
-r		_ , ,_,	•		
		_ , ,_,			
tp://ec.europ	a.eu/consumers/consu	umers safety/safety p	products/rapex/alerts/main/?		
			Excel version 🐹		
	event=n	nain.weeklyReportPrir	ntVsn&web_report_id=1851)		
(http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/main/?					
			Printable version 📥		
		event=r	tp://ec.europa.eu/consumers/consumers_safety/safety_p event=main.weeklyReportPrir tp://ec.europa.eu/consumers/consumers_safety/safety_p		

# Weekly overview report on consumer products

# Serious risk







Name: Rento TAPA KYLPEÄ - löylytuoksu talven mausteet (Winter Spices sauna scent)

Type/number of model: 276437

Batch number/Barcode: EAN Code: 6410412764379

#### Risk: Chemical

The product lacks the appropriate labelling and warning of danger as required for hazardous substances (skin sensitising, skin irritating and eye irritating). The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP).

**Measures taken by economic operators:** Destruction of the product (By: Distributor) **Measures ordered by public authorities:** Withdrawal of the product from the market





(http://ec.europa.eu/consumers/images

#### Alert number: A12/0483/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0483/16&exclude\_search\_term=0&search\_year=2016)

Category: Chemical products

Product: Tattoo ink

Brand: Eternal Ink

Name: Solid Gold

Type/number of model: Solid Gold

Batch number/Barcode: batch 20.07.15; production date 2015.08.20; expiry date 2018.07.20

#### Risk: Chemical

The product contains the aromatic amine o-toluidine (measured value 48 mg/kg). Aromatic Amines can cause cancer, cell mutations and affect reproduction. The Council of Europe Resolution ResAP (2008)1 on requirements and criteria for the safety of tattoos and permanent make-up, recommends that aromatic amines with carcinogenic, mutagenic, reprotoxic or sensitising properties should neither be present in tattoos and permanent make-up products nor released from azo-colourants. The product does not comply with the national legislation.

**Measures ordered by public authorities:** Ban on the marketing of the product and any accompanying measures

+ View i	more
----------	------



(http://ec.europa.eu/consumers/images

#### Alert number: A12/0458/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0458/16&exclude\_search\_term=0&search\_year=2016)

Category: Childcare articles and children's equipment

Product: Amber necklace

Brand: Unknown

Name: Mon premier collier d'ambre ('My first amber necklace')

Type/number of model: M 244002 - CA1M

Batch number/Barcode: 3700273401142

Risk: Strangulation

The clasp of the necklace does not break easily enough when under tension and children may be strangled.

**Measures taken by economic operators:** Withdrawal of the product from the market, Recall of the product from end users (By: Distributor)

View more



#### Alert number: A12/0463/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0463/16&exclude\_search\_term=0&search\_year=2016)

Category: Childcare articles and children's equipment

Product: Amber necklace

Brand: creagem

Name: Unknown

Type/number of model: 826

Batch number/Barcode: Unknown

Risk: Strangulation

The clasp of the necklace does not release when under tension: this may cause strangulation.

**Measures taken by economic operators:** Withdrawal of the product from the market, Recall of the product from end users (By: Distributor)



Name: Unknown

Type/number of model: N3-634 (7-14)

Batch number/Barcode: Unknown

Risk: Strangulation

The drawstrings in the hood can become trapped during various activities of a child, causing strangulation. The product does not comply with the relevant European standard EN 14682.

**Measures ordered by public authorities:** Ban on the marketing of the product and any accompanying measures





(http://ec.europa.eu/consumers/images

#### Alert number: A12/0469/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0469/16&exclude\_search\_term=0&search\_year=2016)

Category: Cosmetics

Product: Hair straightening product

Brand: Capil'liss system

Name: Crème capilaire lissante - traitement à la nanokeratine - fort - étape 2

Type/number of model: Unknown

Batch number/Barcode: bar code kit 0823550685608

#### Risk: Chemical

The products contain an excessive amount of formaldehyde (measured value up to 4.7%). Formaldehyde may produce irritation of the eyes, the skin and upper respiratory tract; long term exposure may cause cancer. The product does not comply with the Cosmetic Products Regulation.

Measures taken by economic operators: Recall of the product from end users (By: Importer)

3/5/2016



(http://ec.europa.eu/consumers/images

#### Alert number: A12/0480/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0480/16&exclude\_search\_term=0&search\_year=2016)

Category: Decorative articles

Product: Decorative candles

Brand: PARTY FIESTA

Name: Candles

Type/number of model: CUPCAKE 191924

Batch number/Barcode: 1919240010009

#### Risk: Choking

The candles, due to their characteristic form, colour and size may be mistaken for foodstuff. Small parts can be easily detached from the product and this may lead children to put them in the mouth, swallow or ingest them. The product does not comply with the requirements of the Directive 87/357/EEC on products which, appearing to be other than they are, endanger the health or safety of consumers.

Measures ordered by public authorities: Withdrawal of the product from the market

➡ View more



(http://ec.europa.eu/consumers/images

Alert number: A12/0476/16
(http://ec.europa.eu/consumers/consumers_safety/safety_products/rapex/alerts/main/?
event=main.notification&search_term=A12/0476/16&exclude_search_term=0&search_year=2016)
Category: Electrical appliances and equipment
Product: Mobile phone with charger
Brand: XIAOMI
Name: Unknown
Type/number of model: Charger: CH-P002
Batch number/Barcode: Unknown
Risk: Electric shock
The insulation between the primary and the secondary circuit of the charger is not sufficient, which may

cause an electric shock. The pins of the converter plug adapter do not have an insulating collar, so when inserting the plug the user may touch the live pins. The plug adapter allows single-pole insertion of the charger, leaving the remaining free live pin accessible. The product does not comply with the requirements of the Low Voltage Directive and the relevant standards EN 60950 and IEC 60884.

**Measures ordered by public authorities:** Withdrawal of the product from the market, Recall of the product from end users

View more



(http://ec.europa.eu/consumers/images

#### Alert number: A12/0490/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0490/16&exclude\_search\_term=0&search\_year=2016)

Category: Electrical appliances and equipment

Product: Electric griddle pan

Brand: THULOS

Name: Electric Grill

Type/number of model: TH-PA 461

Batch number/Barcode: 8436550620535

#### Risk: Burns, Electric shock

Live electrical connections are accessible. The stainless-steel sides of the appliance become too hot. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 60335.

Measures ordered by public authorities: Withdrawal of the product from the market





(http://ec.europa.eu/consumers/images

#### Alert number: A12/0892/15

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0892/15&exclude\_search\_term=0&search\_year=2016)

Category: Electrical appliances and equipment

Product: Mains extension lead

Brand: AOBOER

Name: Unknown

Type/number of model: GBK10

Batch number/Barcode: Unknown

Risk: Electric shock

The plastic is not sufficiently resistant to heat and live parts could become accessible as a consequence. The product does not comply with the requirements of the Low Voltage Directive and the relevant European standard EN 20315.

Measures ordered by public authorities: Import rejected at border



(http://ec.europa.eu/consumers/images

Alert number: A12/0461/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0461/16&exclude\_search\_term=0&search\_year=2016)

Category: Furniture

Product: Folding chairs

Brand: MAXCHIEF EUROPE

Name: Taburete plegable ("folding stool")

Type/number of model: 1) PC-24 Markus model 2) PC-24N-W Arianne model

Batch number/Barcode: Unknown

Risk: Injuries

The chairs are unstable, which may lead to the user falling, possibly causing injury. The product does not comply with the relevant European standard EN 1022.

Measures ordered by public authorities: Import rejected at border





Alert number: A12/0482/16

(http://fc1.eu/onsumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0482/16&exclude\_search\_term=0&search\_year=2016)

Category: Gas appliances and components

Product: Gas barbecue

Brand: SMEG

Name: Unknown

Type/number of model: BIBQ1205F BIBQ1205H

Batch number/Barcode: 8017709184988 8017709184995

#### Risk: Fire

In specific circumstances, a process of galvanic oxidation could be triggered, which could create a small hole in the fuel pipe of one of the burners, resulting in a gas leak. Given that the hole is always downstream of the burner's gas tap, the risk is not present when the appliance is not being used. The product does not comply with the requirements of the Gas Appliances Directive and the relevant European standards EN 498, EN 30-1-1 and EN 437.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

View more



#### Batch number/Barcode: Bar code: 5050577588369

#### Risk: Chemical

The separators of the double glass wall of the flask contain asbestos fibres. If the flask breaks, the user may inhale asbestos fibres, which are carcinogenic. The product does not comply with the REACH Regulation.

**Measures ordered by public authorities:** Temporary ban on the supply, offer to supply and display of the product





(http://ec.europa.eu/consumers/images

#### Alert number: A12/0467/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0467/16&exclude\_search\_term=0&search\_year=2016)

Category: Machinery

Product: Submersible pump

Brand: Heidmann

Name: Pompa rozdrabniacz / Tauchmotorpumpe

Type/number of model: G81423

Batch number/Barcode: 5901477121944

Risk: Electric shock

The conductors in the cable are too thin. Overheating of the cable can cause parts of the insulation of the cable to disintegrate and thereby expose live sections of the cable which may be touched. Furthermore, there is a risk that the water pumped out will be under voltage. The product does not comply with the requirements of the Machinery Directive and the relevant European standard EN 60335.

Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer)





Rapid Alert System Weekly overview report - European Commission

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0468/16&exclude\_search\_term=0&search\_year=2016)

Category: Machinery

Product: Submersible pump

Brand: Heidmann

Name: Pompa do SzambaTauchmotorpumpe

Type/number of model: H00605

Batch number/Barcode: 5901477122613

Risk: Electric shock

The cables are not correctly marked. It is thus impossible to assess whether the cable meets the requirements of heavy-duty rubber-insulated cables. There is a risk that the cable is not suited to contact with water and that the user could consequently receive an electric shock on contact with the water. The product does not comply with the requirements of the Machinery Directive and the relevant European standard EN 60335.

Measures taken by economic operators: Withdrawal of the product from the market (By: Retailer)



#### Batch number/Barcode: 2009610021770

#### Risk: Electric shock

The housing is not strong enough and could break. The user could consequently come into contact with live parts. Not all necessary safety warnings are provided. The product does not comply with the requirements of the Machinery Directive and the relevant European standard EN 60745.

Measures ordered by public authorities: Withdrawal of the product from the market

➡ View more



#### Alert number: A12/0464/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0464/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

**Product:** Passenger car

Brand: VW

Name: Touareg

**Type/number of model:** Type-approval number: e1\*2007/46\*0376\*00; e1\*2007/46\*0403\*00; e1\*2007/46\*0498\*00\*; e1\*2007/46\*0499\*00; Type: 7P, 7PH

**Batch number/Barcode:** The vehicles affected were produced between March 2010 and 19 January 2016.

#### Risk: Injuries

The brake pedal pivot pin may become dislodged with the consequence that it is no longer possible to activate the brakes fully.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)



#### Alert number: A12/0465/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0465/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Van

Brand: Citroen

Name: Jumper

Type/number of model: EC type-approval: e3\*2001/116\*0234\*12 Type: Y

**Batch number/Barcode:** The vehicles concerned were manufactured between 27 July 2015 and 1 August 2015.

Risk: Injuries

The screws on the break-in protection plate on the sliding side door may break over time. In the event of an accident, this may result in the sliding door opening of its own accord.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

View more

#### Alert number: A12/0466/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0466/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Van

Brand: Boxer

Name: Peugeot

Type/number of model: EC type-approval: e3\*2001/116\*0233\*12 Type: Y

**Batch number/Barcode:** The vehicles concerned were manufactured between 27 July 2015 and 3 August 2015.

Risk: Injuries

The screws on the break-in protection plate on the sliding side door may break over time. In the event of an accident, this may result in the sliding door opening of its own accord.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

➡ View more

Alert number: A12/0473/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0473/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Motorcycle

Brand: Triumph

Name: Street Twin and Bonneville T120

Type/number of model: Type Approval Numbers: E11\*168/2013\*00204, E11\*168/2013\*00207.

Batch number/Barcode: Vehicles produced from 07/09/2015 to 11/11/2015

#### Risk: Fire

There is a risk of a fuel leak via the fuel pump sub harness which could lead to a fire.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

View more

#### Alert number: A12/0474/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0474/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Passenger car

Brand: Honda

Name: FR-V, Civic Hybrid, Jazz, Jazz Hybrid, Legend, CR-V and RIDGELINE

Type/number of model: Unknown

Batch number/Barcode: Vehicles produced from 02/03/2004 to 20/05/2015

Risk: Injuries

Abnormal deployment pressure may lead to rupture of the driver's air bag inflator case. In this event, metal fragments could be propelled into the passenger compartment, potentially causing injury to a vehicle occupant.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

#### Alert number: A12/0475/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0475/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Passenger car

Brand: Ford

Name: Explorer

Type/number of model: Unknown

Batch number/Barcode: Vehicles produced from 01/02/2011 to 30/11/2012

#### Risk: Injuries

The interior door handles may crack, allowing the handle return spring to become unseated and not return to the fully closed position. In extreme circumstances this could allow the door to open unintentionally, posing a risk to vehicle occupants and other road users.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

➡ View more

#### Alert number: A12/0484/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0484/16&exclude\_search\_term=0&search\_year=2016) Category: Motor vehicles

Product: Passenger car

Brand: BMW

Name: 7 Series

Type/number of model: Type: 7 L. EC type-approval: e1\*2007/46\*0276. Model: G11 and G12

Batch number/Barcode: The vehicles affected were produced between October 2014 and June 2015.

Risk: Injuries

There might be a metallic stamping residue inside the housing of the airbag control unit. In case of a crash, it might come into contact with the circuit board and cause a short circuit. As a result, the airbags would not deploy, thus increasing the risk of injury to the occupants.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

➡ View more

Alert number: A12/0486/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0486/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Passenger car

Brand: Jaguar

Name: XF

Type/number of model: Unknown

Batch number/Barcode: Vehicles produced from 23/09/2008 to 16/01/2009

Risk: Fire

Rapid Alert System Weekly overview report - European Commission

The fuel outlet flange mounted in the fuel tank can crack and leak fuel vapour or liquid fuel. This could lead to a pool of fuel underneath the rear of the vehicle, which in the presence of an ignition source could lead to a fire.

#### Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

➡ View more

#### Alert number: A12/0487/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0487/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Passenger car

Brand: Ford

Name: Kuga

Type/number of model: Unknown

Batch number/Barcode: Vehicles produced from 15/01/2008 to 17/05/2010

Risk: Fire

The heated washer jets may have jet heating elements which are not correctly sealed. There is a possibility that poor sealing could lead to corrosion due to water ingress and subsequent overheating of the jets which could lead to a fire.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

View more

#### Alert number: A12/0488/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0488/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Passenger car

Brand: Jaguar

Name: XE

Type/number of model: Right hand drive vehicles.

**Batch number/Barcode:** Only right hand drive vehicles are affected. Vehicles produced from 09/02/2016 to 14/03/2016

#### Risk: Injuries

The Restraints Control Module harness connector has the passenger side pre-tensioner wired to the driver's side connection and driver's side pre-tensioner to the passenger side connection. In this condition, in the event of an accident where the pre-tensioner system would deploy and the passenger seat is unoccupied, the driver's seat belt pre-tensioner will not deploy. As a result, the driver will not be restrained as intended and the risk of injury to the driver may be increased.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)

View more

#### Alert number: A12/0491/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/?

Rapid Alert System Weekly overview report - European Commission

event=main.notification&search\_term=A12/0491/16&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Motorcycle

Brand: Kawasaki

Name: ZX1000SG

Type/number of model: Ninja ZX10R 2016

Batch number/Barcode: Unknown

Risk: Injuries

The steering damper bracket bolts may have been excessively tightened during assembly. This could cause them to break and interfere with the steering.

Measures taken by economic operators: Recall of the product from end users (By: Importer)

➡ View more



(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/1346/15&exclude\_search\_term=0&search\_year=2016)

Category: Motor vehicles

Product: Motorcycle

Brand: KTM

Name: 250, 350, 450 SX-F

Type/number of model: Model year: 2016

Batch number/Barcode: 2016 vehicles

Risk: Fire

#### 3/5/2016

Defective fuel hoses may cause uncontrolled fuel leaks at the bends in the hoses or at the hose ends. This may lead to a fire.

### Measures taken by economic operators: Recall of the product from end users

➡ View more



(http://ec.europa.eu/consumers/images

## Alert number: A12/0459/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0459/16&exclude\_search\_term=0&search\_year=2016)

Category: Protective equipment

Product: Equestrian helmet

Brand: LAS

Name: New Dragon

**Type/number of model:** Model: white RG 0637/102. Helmet 1: 907F00052X1, size 52 Helmet 2: 907F00054X2, size 54 Helmet 3: 907F00056X3, size 56

Batch number/Barcode: Helmet 1: 06.2005; Helmet 2: 02.2008; Helmet 3: 07.2013.

#### Risk: Injuries

The helmet does not adequately absorb impacts. Moreover, the retention system is not sufficiently strong and might break, leading to head injury in the event of a fall or impact. The product does not comply with the requirements of the Personal Protective Equipment Directive and the relevant standard EN 1384.

**Measures taken by economic operators:** Withdrawal of the product from the market, Recall of the product from end users (By: Distributor)

➡ View more

2



Alert number: A12/0462/16

(http://ep.europa.eu/consumers/consumers/safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0462/16&exclude\_search\_term=0&search\_year=2016) w16/2016-w16\_20166-1f.jpg)

Category Protective equipment

Product: Welding gloves

Brand: Würth

Name: Welderking

Type/number of model: 0984 325 10

Batch number/Barcode: 4045989114191

Risk: Chemical

The amount of Chromium (VI) in the leather of the gloves is too high (measured value: 7.3 mg/kg). Chromium (VI) is sensitising and may trigger allergic reactions. The product does not comply with the REACH Regulation and with the requirements of the Personal Protective Equipment Directive.

Measures ordered by public authorities: Import rejected at border





(http://ec.europa.eu/consumers/images

#### Alert number: A12/0460/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0460/16&exclude\_search\_term=0&search\_year=2016)

Category: Toys

Product: Wooden toy car

Brand: BESTTOY

Name: Unknown

Type/number of model: Unknown

Batch number/Barcode: 4016096335069; 147287

Risk: Chemical

The amount of nickel released by the tyre rivets of the toy car is too high (measured value up to 2.63  $\mu$ g/cm<sup>2</sup>/week). Nickel is a strong sensitizer and can cause allergic reactions if present in articles that come into direct and prolonged contact with the skin. The product does not comply with the REACH Regulation.

Measures taken by economic operators: Withdrawal of the product from the market (By: Distributor)

➡ View more



(http://ec.europa.eu/consumers/images

#### Alert number: A12/0472/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0472/16&exclude\_search\_term=0&search\_year=2016)

Category: Toys

Product: Plastic balls

Brand: X-BD

Name: FLASHING BALLS

Type/number of model: Mod 2336 (75-1)

Batch number/Barcode: 8435353223363

#### Risk: Choking

The toys contain small parts (the squeaking mechanism) that are easily removable. A small child might put them in the mouth and choke on them. The product does not comply with the requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

#### Measures ordered by public authorities: Import rejected at border

➡ View more



(http://ec.europa.eu/consumers/images/rapex/2016w16/2016-w16\_20195-1f.jpg)

# Alert number: A12/0477/16

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/alerts/main/? event=main.notification&search\_term=A12/0477/16&exclude\_search\_term=0&search\_year=2016)

Category: Toys

Product: Fancy-dress cape

Brand: IKEA

Name: LATTJO bat cape

Type/number of model: 603.116.50

Batch number/Barcode: Unknown

#### Risk: Strangulation

The fabric hook and loop fastener at the neck of the bat cape may not detach readily during use, posing a risk of strangulation to children. 3 incidents reported. The product does not comply with the requirements of the Toy Safety Directive.

Measures taken by economic operators: Recall of the product from end users (By: Manufacturer)



Other risk levels



Product: Valve oil for musical instruments

Brand: BLUE JUICE

Name: Valve Oil

Type/number of model: Unknown

Batch number/Barcode: 898963000027

Risk: Chemical

The product has an aspiration hazard and lacks the required labelling, child-resistant fastening and tactile warning of danger. Children could accidentally swallow some of the product leading to aspiration toxicity including chemical pneumonia. The product does not comply with the Regulation on the classification, labelling and packaging of substances and mixtures (CLP).

Measures ordered by public authorities: Withdrawal of the product from the market



Rapid Alert System Weekly overview report - European Commission

requirements of the Toy Safety Directive and the relevant European standard EN 71-1.

Measures ordered by public authorities: Withdrawal of the product from the market

View more

# Disclaimer en de fr

# Important notice for re-use of notifications en

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/docs/notice\_en.pdf)

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/docs/notice\_de.pdf)

(http://ec.europa.eu/consumers/consumers\_safety/safety\_products/rapex/docs/notice\_fr.pdf) *Please be aware that proprietary brands, designs and logos that appear in this listing may have been used by economic operators in violation of intellectual property rights and thus without the legitimate owner's knowledge* 

and/or permission.

If not specified in the report, the risk and non-compliance refer to the risk to consumers' health and safety.

Back to top
 Back to
 Back to
 Back to
 Back to
 Back to
 Back
 Back to
 Back
 Back

Last update: 22.04.2016